
HARTZELL

**Propeller Owner's
Manual & Log Book**

HARTZELL PROPELLER INC. ③

INSPECTION

CODE NO. 81C3F

DATE 2-23-

☒ NEW ☐ REPAIR

C208340

HARTZELL ORDER NO.

PART NUMBER

43186

PHC-C34F-IRF/F7691

ASS'Y SER NO.

GOV. NO.

BULKHEAD NO.

VALVE NO.

EE2277A

N/A

N/A

N/A

BLADE NUMBERS

1

2

3

4

5

6

H86912

H86910

H86920

CARTON NO.

LBS.

WEIGHT

KILOS

HEIGHT

WIDTH

LENGTH

PACKING

COMMENTS:

A2476-9 SPIN. MT. KIT INSTALLED

P25EH

12.8 12.8 L.P. @ 30" RADIUS

SOLD TO:

CUSTOMER ORDER NO.

INSP. BY

BERYL D'SHANNON AVIATION INC.

DSP0135

REV. 1-88

E

N877DM DATE 05-07-14 TACH 4033.55 PROPELLER LOG
Ran up aircraft, removed spinner, dressed blades, lubricated propeller hub, no applicable propeller AD's due at this time. Reinstalled spinner, **This propeller has been inspected i/a/w an 100 hr inspection and found to be in an airworthy condition at this time.**
Lance Milko AP [REDACTED]

Lance Milko AP

Lance Milko AP

Haltom Aircraft Services

Denton TX 76207

TACH
TIME

DESCRIPTION OF WORK

SIGNATURE

N877DM Prop S/N EE2277A Tach: 4078.86 TTSN: 991.03 TTSOH: 212.74

Ran up aircraft. Removed spinner. Dressed blades. Lubricated hub with Aeroshell #22 grease. Reinstalled spinner. This propeller has been inspected in accordance with a 100 hour inspection as per Hartzell Propeller Manual No. 115N and found to in airworthy condition.

John N. Prickett A&P

6/11/15

I certify this engine has been inspected in accordance with annual inspection and was found to be in airworthy condition.

Gary Haltom, A&P