



Photo 1 – View of the left propeller, separated crankshaft, and left engine. (Image supplied by Hartzell)