



Photo 1 – 40-foot trees struck by N9582L.



Photo 2 – Inverted right side of N9582L.



Photo 3 – The propeller still attached to engine after removal from crater.