

Communication Summary

April 15, 2016

Information From: Mr. Richard Ball, Recovery Company



Summary & Factual Information: Mr. Ball was asked to confirm if any fuel was found in the accident airplane. He indicated that his recovery personnel found no fuel in the recovered airplane.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator