

-----Original Message-----

From: Ryan Arroyo [REDACTED]

Sent: Friday, April 01, 2016 8:53 AM

To: Hand, Ken (FAA)

Subject: Statement - Arroyo

The incident occurred at Shiprock airport at around 11:30a on March 31, 2016. We flew overhead and saw that the windsock was at 5knots in the 200 direction. We also checked Farmington ATIS which was reporting calm winds. We then entered left downwind for Rwy 20. Joe Tumminaro was flying the airplane at this point.

After landing in the three point configuration, the airplanes left wing lifted up, which pushed the airplane off to the right. We exited the runway at a 45 degree angle. The gear hit a deep irrigation ditch located off the right side of the runway, which tore the gear off, spinning the aircraft around and then ultimately flipping it over on its roof, where it came to rest.

Ryan Arroyo