

Communication Summary

May 10, 2016

Information From: Todd A. Laps, Public Safety/Operations
Manager



Summary & Factual Information:

Mr. Laps was asked to search for the missing bolt. He, in part, indicated that they swept the runway and taxiway with brooms after the incident, and they have not found any loose bolts at this point.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator