



Photo 1 – Pre-accident photograph of N4234Z, showing a 90-gallon Sorensen tank on bottom of fuselage. The front of the tank is about 2 inches aft of the front of the landing gear leg.



Photo 2 – N4234Z at the accident site.