



Aircraft accident report of N576RV

On August 18th 2016 at approximately 3:10pm. Stanley Tinker owner of N576RV departed runway 27, crashing shortly thereafter. I was called by Stanley Tinker asking for assistance and informing me he had crash the aircraft. I arrived on the accident site and found Stanley awake and alert then asked him what had happened; he stated to me he had left the canopy unlatched and it came open during takeoff which caused the aircraft to pitch forward and hit the runway. I then noticed fuel leaking from the aircraft at a rapid rate, secured the master switch and mag switch then called 911.

Nicholas Keith
Keith Aero Inc.

