


Sept 2, 2016

On August 29, 2016 N91488 landed on runway 18 at Monett Regional Airport (HFJ) at 9:30 am. Weather was clear wind 120 at 4. Pilot was the only person on board. Normal approach, on touchdown pilot noticed right wing lower than left wing and the aircraft started pulling to the right. Left the runway, down an embankment and through a four strand barbed wire fence. Aircraft came to a full stop. Pilot departed the aircraft with no injuries. Aircraft's right gear was collapsed. Local personnel called a wrecker and aircraft was lifted up and manually put right gear down and locked. Towed the aircraft to vacant hangar at (HFJ).

Respectfully submitted,


Donald P. McMahon

Owner and Pilot of N91488