

| YEAR<br>20<br>DATE | RECORDING<br>TACH<br>TIME | TODAY'S<br>FLIGHT | TOTAL<br>TIME IN<br>SERVICE | Description of Inspections, Tests, Repairs and Alterations<br>Entries must be endorsed with Name, Rating and Certificate Number of<br>Technician or Repair Facility. (See back pages for other specific entries.) |
|--------------------|---------------------------|-------------------|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|--------------------|---------------------------|-------------------|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

06-06-2016 N2810X 5941.02 TACH 11,941.48 TT 249.48 SMOH

Annual Inspection-----Compression Test: All 77/80 or better. Cleaned, gapped and rotated spark plugs. Checked mag to engine timing. Installed new BA5705 air filter element. Cleaned and checked oil screen.

AD04-10-14C1 due at o-haul, prop strike, or sudden stoppage.

I certify that this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

07-05-2016 N2810X 6098.60 TACH 12,099.06 TT 407.06 SMOH

Cleaned, gapped, and rotated spark plugs. Retimed mags to engine. Cleaned and checked oil screen. Installed new BA5705 air filter element.