

G. On-Site Discussions: Procedures, Routines, Ops manual, Mx manual,

ACFT RECENTLY PURCHASED, (REVIEW SALES SHEET FOR AIRCRAFT
INFO)

RADAR - APPEARS WILEY POST TO CHICKSA^{SP}, ON RETURN LEG,
CHK
ACCIDENT; ACFT SLOWED DOWN BEFORE DISAPPEAR OFF RADAR

ACFT INSURED THRU ADPA, [REDACTED]

MX LOGS AT RESIDENCE, FATHER/FAA WILL GET

WITNESS - ACFT SPINNING, (FROM HIGH ALTITUDE) TO GROUND, LARGE
FIREBALL, ARRIVED ONLY A COUPLE MINUTES DFT, LARGE FIRE

HOMEOWNER, DIDN'T SEE IT, BUT HEARD SOMETHING, ENGINE DIDN'T
SOUND RIGHT, 'CUTTING-W-OUT', LOTS OF FIRE AND SMOKE

TURNED WATCH, (DAMAGED) OVER TO PILOT'S FATHER