

ENGINE DATA
(THIS PAGE MUST BE FILLED OUT COMPLETELY)

MANUFACTURER NSI MODEL SHO EA81 SERIAL NO. 244159

DISPLACEMENT 1.8L OIL PRESSURE MAX. 79 MIN. 12 OIL TEMP MAX. 240 MIN. 50

WEIGHT _____ RATED H.P. 124.3 AT 6472 R.P.M. _____

OIL GRADE: SUMMER 20W50 ~~10W40~~ WINTER 5W30 OIL CAPACITY 4.0LS

FUEL MINIMUM OCTANE 82 FIRING ORDER 1342

MAGNETO TIMING - MAGNETO POINT SETTING -

SPARK PLUG GAP .035"

ADDITIONAL ENGINE DATA — NON-AIRCRAFT ENGINE

Engine Manufacturer ~~(NSI) NORTHWEST SERVICES, INC.~~ RAM PERFORMANCE
Name

~~19730 55th DR. N.E.~~
Complete Address

Original Engine Use SUBURU CAR

Sources of parts and information for this engine FA81

RECORD OF OWNERSHIP

Michael S. LOGAN

(OWNER)

(STREET ADDRESS)

LUSBY, MD

12/9/95

(CITY & STATE)

(DATE PURCHASED)

(DATE SOLD)

Michael S. Logan

(OWNER)

(STREET ADDRESS)

La Vernia, TX 78121

(CITY & STATE)

(DATE PURCHASED)

(DATE SOLD)

(OWNER)

(STREET ADDRESS)

(CITY & STATE)

(DATE PURCHASED)

(DATE SOLD)

ENGINE LOG

YEAR		DESCRIPTION OF INSPECTIONS, REPAIRS AND ALTERATIONS Certificated mechanics or repair facilities must endorse all inspections and repairs on type certified aircraft with name, rating & Cert. No.
MO.	DAY	
2013	10	13 Condition inspection - large oil 20W50-35QTS filter PA2870A PLUGS OK move oil cooler to left side of radiator - move radiator inside cowling
	5	4 B+M oil cooler in series with current cooler
	4	23/02 I certify that this aircraft has been inspected on 23 April 2005 in accordance with the scope of detail of appendix D to part 43 and was found to be in condition for safe operation
	5	24 replace power CBs with W31-X2 M16-10 busbar switches
	6	25 install battery isolator SURE POWER model 702 s/p C160 08540