

N 1400 P

5870 OBSCT

387-03256 N 25440-48E

3/1/2012

LYCOMING

ENGINE LOG

SSP-1872-1

LYCOMING

652 Oliver Street
Williamsport, PA 17701 U.S.A.
570/323-6181

ENGINE LOG AND MAINTENANCE RECORD

RECORD OF LYCOMING FO-540-C4B5 L-25440-48E
MAKE MODEL SERIAL
FROM 12/19/2011 20 TO 20
DETAILING TIME FROM AL Jack 1970 hrs TO
HOURS HOURS

SSP-1872-1

© 1994 by Textron Lycoming "All Rights Reserved"

October 1994

LYCOMING

A Textron Company

652 Oliver Street
Williamsport, PA. 17701 U.S.A.

Form No. 2480 (3/04-LM)

License
Number

This engine has been overhauled in accordance with the applicable Lycoming specifications. All applicable Federal Aviation Administration Airworthiness Directives and Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are new, newly rebuilt or newly overhauled. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model:

Serial #: **L-25440-48E**

Total Time: **1417.3**

Work Order #: **AR520368**

Date Completed: **12/19/11**

Authorized Signature

Lycoming Engines

652 Oliver Street

Williamsport, PA. 17701
Repair Station: EJ1R115K

a

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
10-4-16			2380.8 hrs Changed Engine oil and Filter serviced with 12 qts Acrosnell W-100 and CH48110 Filter Run-up and Leak Check Good [REDACTED] [REDACTED]		

N1400P Annual Inspection

8 Feb 17 Tach/ACTT 2392.0 Hrs. Engine TSMOH 422.9 Hrs. Compression check #1(74 #2) 70 #3) 70 #4) 74 #5) 72 #6) 76/80. Noted engine oil at 10qts & installed new oil filter CH48110. Checked fuel and oil screens and hoses. Inspected wiring, accessories, and magneto timing. Inspected exhaust system, checked induction system, fuel control and all other controls. Installed (4) new spark plugs P/N REM38E. Cleaned, gaps, and rotated spark plugs. Checked engine mount propeller and spinner. Replaced all valve cover gaskets with new. Installed new engine air filter P/N BA3205. Engine run and checked for leaks and performance. C/W AD 2015-19-07 Fuel injection lines, due each 100 hrs next due at 2492.0 Hrs. AD 2015-02-07 prop gov shaft N/A by model number. I certify this Engine has been inspected in accordance with an annual inspection and is determined to be in an airworthy condition.

[REDACTED]
RYAN DULAS [REDACTED]

ACR ELECTRONICS, Inc.
Artex Products - CAGE Code 18560
Fort Lauderdale, FL 33312

LOG BOOK ENTRY

10-14-15

E.L.T. BATTERY

REPLACEMENT DATE

NOV 2021

N1400P

4/24/08



The Standard

AIRCRAFT LOG

ASA-SA-1

YE/ , N1400P Annual Inspection

8 Feb 17 Tach 2392.0 Hrs, A/C TT 2392.0 Hrs. Engine TSMOH 422.9 Hrs. Prop TSMOH 257.8. Hrs.

DA1 Heater Hobbs 313.0 hrs. ELT Battery Date Nov 2021. Checked ELT per 91.207(D)(1-4). Installed new wheel bearings and races in RH & L/H main gear. Replaced L/H gear trailing link brass bushings (2) P/N 2-4101-199. Greased gear and repacked wheel bearings. Checked gear retraction and emergency extension. Serviced hydraulic reservoir and filter. Replaced trim lever return springs. Replaced throttle and mixture cables with new, P/N 45748. Replaced (8) push/pull rod ends as required, P/N 0006-1, and (2) threaded rod ends P/N HM5-3. Checked control surfaces for proper travels.

. C/W AD 2004-25-16R1 Janitrol heater fuel regulator due @ 2429.8 Hrs AD 2004-21-05 Janitrol heater pressure decay test due @ 398.4 hrs heater hobbs or Feb 2018. I certify this Aircraft has been inspected in accordance with an annual inspection and is determined to be in an airworthy condition. -----

RYAN DULAS

5-12-17	Tach	2433.0 hrs	Installed Overhauled D.G PLW 4000B-12
			SLW 31881C. Removed F/ed trim valve and
			Replaced seals.

N14002

PROPELLER LOGBOOK

PROPELLER MODEL HC-E34R-1DLF

PROPELLER S/N FM-464

LOGBOOK #

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			WV-105-21V-KRIBB10X ORIGINATED DATE PHONE NO 518-482-1121 WILSON PROPELLER CO
1-24-14			TACH READS 2155 HRS 20 SPON
			CHECK PROP BLADES FOR NICKS, CHECKED HUB
			FOR LEAKS NONE FOUND
1-20-15			TACH READS 2230 HRS PROP CHECKED
			N1400P Annual Inspection
			3 Feb 16 Tach/ACTT 2329.8 Hrs, Prop TSMOH 194.8 Hrs
			Inspected propeller blades, hub, spinner, and bulkhead for condition and mounting in accordance with an annual inspection.
			N1400P Annual Inspection
			8 Feb 17 Tach/ACTT 2392.0 Hrs, Prop TSMOH 257.8 Hrs
			Inspected propeller blades, hub, spinner, and bulkhead for condition and mounting in accordance with an annual inspection.
			RYAN DULAS