



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: December 1, 2016 / December 5, 2016
Person Contacted: Greg Sheehan – FAA Flight Standards
NTSB Accident Number: CEN17LA044 – Bridgeport, Texas

Narrative:

Inspector reported that the accident site was located about 400 to 500 yards past the end of the runway, and that the airplane had impacted a tree during the accident sequence.

----- End of entries -----