



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: December 13, 2016
Person Contacted: Trooper Patrick Garcia – Texas Highway Patrol
NTSB Accident Number: CEN17LA044 – Bridgeport, Texas

Narrative:

Trooper Garcia responded to the accident site. He reported that while on-scene, the pilot and passenger independently stated that the fuel selector was in the “wrong” position. They informed him that they had stopped at the Bridgeport airport for fuel and had forgotten to reposition the selector before takeoff.

----- End of entries -----