

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: GAINSVILLE State: TEXAS

ZIP: 76240 Country: USA

Latitude: N33 39.51' Longitude: W97 11.89'

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 02/21/2017 Local Time: 00:15
mm/dd/yyyy

Time Zone: CST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N6343L

Manufacturer: AMERICAN AVIATION

Model: AA-1A

Serial Number: AA1A-0343

Year of Manufacture: 1972

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1500 lbs

Weight at Time of Accident/Incident: 1400 lbs

Number of Seats: 2 Flight Crew Seats: _____

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☒ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

- ☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	LYCOMING	O-235-C2C	L-10806-15	01/8/1972	108	2133	39	375
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 08/26/2016
mm/dd/yyyy

Airframe Total Time: 2094 hrs

hours measured at (Select one)

- ☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: _____

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: McCauley

Model: 1A105SCM7154

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: AMERIKING CORP

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☒ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: BRADLEY TODD KELLYCity: LEWISVILLEState: TEXASZIP: 75067Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: GAINSVILLEDistance From Airport Center: 0 smAirport Identifier: KGLEDirection From Airport: AT AIRPORT degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 845 ft. msl**Runway Information**Runway ID: 18-36 (L/R/C) Length: 6000 ft Width: 1000 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☒ Wet
☐ Rubber Deposits ☒ Soft
☐ Slush-Covered ☒ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☒ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☒ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: ULUG City of Residence: CARROLLTON
 Middle Initial: S State: TEXAS ZIP: 75007
 Last Name: BAYRAMOGLU Country: USA
 Age at time of Accident/Incident: 40 Date of Birth: mm/dd/yyyy
 Certificate Number:

Degree of Injury ☐ None ☐ Fatal ☒ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☒ 3-point</td> <td>☒ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☒ 3-point	☒ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☒ 3-point	☒ 3-point																
☐ 4-point	☐ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer																	

Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance	Date of Last Medical <u>03/30/2015</u> mm/dd/yyyy
---	---	---	--

Medical Certificate Limitations

NONE

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>01/23/2016</u> mm/dd/yyyy	Flight Review Aircraft Make: <u>CESSNA</u> Model: <u>172M</u>
---	--

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☒ None ☐ Instrument Airplane ☐ Airplane Single-Engine ☐ Instrument Helicopter ☐ Airplane Multi-Engine ☐ Helicopter ☐ Gyroplane ☐ Glider ☐ Powered Lift ☐ Sport
---	---	--	--

Type Ratings	Student Endorsements (Include dates) NONE IFR STUDENT with 16hrs dual received
---------------------	---

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	463	31	463	0	67					
Pilot in Command (PIC)	421	31	421	0	63					
Time as Instructor	0	0		0	0					
This Make/Model					7					
Last 90 Days	61	31	61	0	18					
Last 30 Days	23	6	23	0	6					
Last 24 Hours	5	4	5	0	4					

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

“Flight Crewmember 2” was pilot flying ☐ Yes ☒ No

First Name: BRADLEY

City of Residence: LEWISVILLE

Middle Initial: T

State: TEXAS ZIP: 75067

Last Name: KELLY

Country: USA

Age at time of Accident/Incident: 47 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: IN PROCESS

Degree of Injury ☐ None ☐ Fatal ☐ Minor ☐ Unknown ☒ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single	Restraint Type Available ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☒ Student ☐ Sport ☐ Flight Engineer			
Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☒ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☒ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance	Date of Last Medical _____ mm/dd/yyyy

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: _____ <i>mm/dd/yyyy</i>	Flight Review Aircraft Make: _____ Model: _____
---	--

Airplane Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
---	--	--	---

Type Ratings N/A FLIGHT LESSONS TAKEN FROM US SPORT AIRCRAFT approximately 16 HOURS DUAL RECEIVED	Student Endorsements <i>(Include dates)</i>
---	--

[illegible]

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)						
Crew Name and Address First Name: <u>N/A</u> City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____			Seat Occupied ☐ Left ☐ Center ☐ Right ☐ Front ☐ Rear ☐ Single ☐ Unknown		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
Crew Name and Address First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____			Seat Occupied ☐ Left ☐ Center ☐ Right ☐ Front ☐ Rear ☐ Single ☐ Unknown		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)						
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints
First Name: <u>N/A</u> City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KGYI</u> City: <u>SHERMAN</u> State: <u>TEXAS</u> Country: <u>USA</u>	Time of Departure Time: <u>23:45</u> Time Zone: <u>CST</u>	Destination Airport ID: <u>KGLE</u> City: <u>GAINSVILLE</u> State: <u>TEXAS</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ Company VFR ☐ Military VFR ☐ VFR ☐ VFR/IFR ☐ IFR ☐ Unknown Activated? ☐ Yes ☐ No ☐ Unknown
--	---	--	--

Type of ATC Clearance/Service (Check all that apply) ☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise ☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA			
Airspace where the accident/incident occurred (Check all that apply) ☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special ☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area ☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown ☐ Class D ☐ Prohibited Area ☐ TRSA ☐ Class E ☐ Restricted Area ☐ FAR 93			Altitude of In-Flight Occurrence: _____ ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply) ☐ National Weather Service ☐ Company ☐ Flight Service Station ☐ Military ☐ TV/Radio ☐ Internet ☒ Automated Report ☐ None ☐ Commercial Weather Service (DUATS) ☐ Unknown ☐ On-Board Weather		Weather Observation Facility Facility ID: <u>KGLE</u> Observation Time: <u>23:58</u> Time Zone: <u>CST</u> Distance from Accident Site: <u>ON SITE</u> nm Direction from Accident Site: <u>ON SITE</u> degrees true																													
Basic Conditions ☒ VMC ☐ IMC ☐ Unknown	Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☐ Day ☒ Night ☐ Bright Night																														
Sky/Lowest Cloud Condition ☒ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered Lowest Cloud Condition Height _____ ft agl	Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown Ceiling Height _____ ft agl	Temperature: _____ (C) or _____ (F) Dew Point: _____ (C) or _____ (F) Altimeter Setting: _____ in. Hg or _____ MB																													
Wind Direction ☐ Variable -or- Direction: <u>150</u> degrees true	Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: <u>5</u> kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts	Visibility <u>10</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: _____ ft																												
Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☒ N/A ☐ Unknown	Type of Precipitation (Check all that apply) ☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals		Restriction to Visibility (Check all that apply) ☒ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown																												
Icing Forecast <table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☒ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>	Amount	Type	☒ None	☒ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		Icing Actual <table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☒ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>		Amount	Type	☒ None	☒ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		Turbulence Type (Check all that apply) ☒ None ☐ Clear Air ☐ Terrain-Induced ☐ Convective Turbulence Severity ☐ Light ☐ Moderate ☐ Severe ☐ Extreme
Amount	Type																														
☒ None	☒ N/A																														
☐ Trace	☐ Rime																														
☐ Light	☐ Clear																														
☐ Moderate	☐ Mixed																														
☐ Severe	☐ Unknown																														
☐ Unknown																															
Amount	Type																														
☒ None	☒ N/A																														
☐ Trace	☐ Rime																														
☐ Light	☐ Clear																														
☐ Moderate	☐ Mixed																														
☐ Severe	☐ Unknown																														
☐ Unknown																															

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet if necessary)

Aircraft landed approximately 250ft short of runway after power failure. Ground was wet and muddy due to heavy rainfall from the day before.
Right main and nose gear collapsed, damaging / detaching right wing. Fuel tanks in this aircraft are wing spars, it severed it from fuselage draining fuel on the ground.
Left wing retained landing gear but it was damaged from being sucked into mud, causing twisting left rear section of fuselage.
Due to nose gear collapsing, engine suffered prop strike. Since the engine was not running, only one blade hit the ground.
Seats and most of the cockpit was not damaged. Photographs are included.

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

"@" stands for approximate.

Performed an emergency landing while executing a go around due to power failure.

1/11/2017 Bradley wanted to progress in aviation and purchased N6343L from New York. He asked his close friend Ulug to fly it back with him on right chair. Plane flew great but it is very slow compared to most general aviation aircraft. It required almost double the runway to take off and climbed half the rate of a 172. It also has a higher stall speed due to small wings. It flew back with no mechanical issues.

2/19/2017 - Day before incident

Flew from Denton DTO to Gainesville GLE @ 7pm CST to go to dinner. Bradley filled it up in Gainesville, receipt from airport internal system is included in documents. Aircraft was secured, a courtesy car was taken to a local restaurant. Up on return, aircraft was preflighted and returned back to Denton which is a 15 min flight. Sectional insert of the flight is included.

N6343L is equipped with 22 gallon usable fuel tanks, at 45% power is rated to burn 5.5gph which was confirmed on the flight back from NY. This allowed for 3 hours of flight with an hour of reserve.

2/20/2017

Bradley and Ulug met @ 9:30pm to fly. Both participated on preflight and took off from DTO to GLE before the tower closed. It did experience radio trouble from upper radio when tower cleared for take off. It was remedied by switching to the bottom radio and it took off from runway 18 heading north east bound to GYI @9:45pm. Fuel showed full at departure on the indicators, knowing 15min of it was used the day before, leaving 3:45mins of flight time including reserve.

Distance to GYI is 40.4nm and it took @ 30 minutes to get there at 45% power running 2250 rpm. GYI has a tower and it was closed on arrival. Intension of flight was to do some touch and go's. Choice of the airport is due to it's 9000ft of runway (ex military). It gave plenty of options for any kind of issues, flying an aircraft that required a long runway for take off and poor climb rate; especially at night.

Winds were 12kt at 160 and all of the pilots were using runway 17L. Pattern was shared with students from US Aviation school. Performed @5 touch and go's before we had a full stop and took a break. After @3 more touch and go's, left the pattern for GLE to fill up and return back to DTO.

5 minutes before GLE, Brad noticed 0 psi on fuel pressure indicator which was in front of him, engine was running smooth. Ulug pushed the electric / aux pump and the needle indicated 5 psi immediately which is the normal operating level. This switch was left on as it was required at landing and take off in most aircrafts for safety.

Atis noted 5kt at 150 with 10mile vis, so it was decided to land at runway 18. This made sense as we were landing south at GYI earlier. Upon a very stable approach, Ulug saw coyote on the runway, decided to execute a go around hoping that the aircraft noise would persuade possible others to leave.

Aircraft was perfectly over the runway and did not touch down as the go around was being executed.

Engine failed during the climb. The aircraft was between 150 to 250 ft off the ground because it has a very poor climb rate.

Bradley has a better memory of when it happened and he notes that it failed as soon as Ulug turned left crosswind.

Ulug knew the airport. It has trees, buildings and power lines (photographed) a head and attempted to land on runway 36.

Aircraft touched down 200 - 300 ft before runway 36. Ground was wet, muddy from heavy rain from the day before.

Ulug exited the aircraft and noticed fuel on the ground, tried to get Bradley out of the plane due to possible fire. This was at @00:15 CST Bradley's left leg was in pain(not broken) due to hard landing on mud which sheared front and right main gears

After assesing the situation for 10 to 15 minutes, both called their wives exactly 00:28 CST. Ulug then called 911 at 00:48 CST and stayed on the phone for 28 minutes.

When the emergency personal arrived, they transported Bradley to Plano medical center. Ulug's wife arrived on the scene and drove him home.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Airplanes give us many tools to deal with emergency situations. One of the critical is altitude. The most dangerous part of aviation is power loss at take off, and it is worse at night. Poor climbing aircraft makes it even more challenging for safe landing.

AA-1A aircraft has small wings and a small engine. Many owners take the O-235 out and put a O-320. GLE is 6000 feet long, any other aircraft would have given more altitude which would have resulted in safe landing.

The small wings and control surfaces did not provide a good decent rate and controllability at lower speeds.

Will only fly AA-1A's at daytime with long runways.

It has been less than 6 weeks, me and Brad are doing great so we are thankful.

It has been a great learning experience but we also understand it was a very isolated incident; power loss at night take off with low altitude in an airport which did not allow landing forward due to hazardous obstacles.

Bradley is looking for a high wing aircraft to purchase, without fuel pumps, good low speed controllability, great glide ratio, simplicity, better track record, i.e. Cessna 172 for safety. Ulug keeps flying but avoids unnecessary night flights.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

5 minutes before we arrived to GLE, Brad noticed 0 psi fuel pressure, engine was running smooth at 45% power @2250 rpm. This engine red lines at 2600 rpm unlike most at 2700. Ulug pushed the electric / aux pump and the needle indicated 5 psi immediately which is the normal operating level.

Total Time/Cycles
On Part

_____ Hours

_____ Cycles

Time Since This Part
Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

20 Gallons

Fuel Type

☒ 80/87

☐ 115/145

☐ Jet B

☐ Other, specify _____

☐ 100 Low Lead

☐ Jet A

☐ JP8

☐ 100/130

☐ Jet A-1

☐ Automotive

Other Services, if Any, Prior to Departure

20 gallons at DTO departure, GYI TO GLE departure indicated fuel was half full and it was safe for a short flight in VMC and calm wind conditions.

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Ulug walked out and Brad was lifted off.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for *other* aircraft)

Aircraft Registration Number

n/a

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed

☐ Minor

☐ Substantial

☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Ulug and Bradley read the Initial investigation, found some discrepancies and would like to clarify for a more accurate report.

"On February 21, 2017, about 0050 central standard time"

Touch down was between 0010 and 0015 for the following reasons.

Ulug got out of the aircraft, walked around, assessed situation and decided with Brad that needed help. This process took approximately 10-15 minutes.

Both Ulug and Bradley called wives, 00:28exact (photo of log included) , then Ulug called 911 0048 and spoke with them for 24 minutes.

"The right wing was found separated from the fuselage and no fuel was observed in the wing spar fuel tank."

Wing spar is this aircraft is a large sized tube which holds fuel in each wing. It is broken in half, this will result in fuel on the ground.

Ulug, airport manager David Vinton and the fire personal will confirm presence of fuel on the ground and smelling fuel. Less than usual caution was used due to ground being wet and muddy.

"The left wing remained attached to the fuselage. The inspector drained the left fuel tank sump drain, which contained a few tablespoons of liquid similar to dirty water."

Bradley filled this aircraft at every fuel stop bringing it back from New York. After every top off, fuel would drain from over flow located bottom inner wing for minutes before take off. When he saw this comment, he sent Ulug the photo of the airplane after the crash. Brad noted since left wing resting at a steep angle; fuel would leak down because the vent is located at the bottom (inner wing).

He also confirms that the right tank was being operated at the time of the landing.

Since the purpose of GLE was to top off N6343L, and having an engine failure during a go around, it would bring out an initial assumption of running out of fuel. As both recall there was more than 45minutes of fuel at arrival of GLE with @2hr20min flight time since top off.

With statements on both tanks in the initial report, it would suggest that the aircraft ran out both tanks simultaneously which is not possible as the aircraft does not have a "both" position on the fuel selector. This was clarified during the formal FAA interview that took place in Gainesville airport two weeks after the incident.

"They departed DTO and executed about 15 touch-and-go landings at North Texas Regional Airport (GYI)"

Ulug made this statement 2 days after the incident to Cristobal Diaz / FAA, as a preliminary statement. Both Ulug and Brad confirms the number of touch and go's were between 7 and 8. At least 5 of the touch and go's were close pattern power off descending 180's to runway 17L, the others were classic since the pattern was being shared with US Aviation students. This was clarified during formal interview.

"During the go-around, the pilot stated that the engine lost power and he made a 180° turn back toward the runway. "

Bradley has a better memory recall on this matter and he said it failed during initial part of left crosswind. With Ulug's poor memory, he recalled that it was during upwind but Ulug agrees that this makes more sense revisiting the field. Therefor it was a descending 90°. This was clarified during formal interview.

This report was generated by both Ulug and Bradley.

Photos and documents are included.

Thank you

Ulug Bayramoglu
Bradley Kelly

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

04/10/2017

mm/dd/yyyy

Name of Pilot/Operator: Ulug S Bayramoglu / Pilot

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: Bradley Todd Kelly

Title: Owner / Operator

Signature: _____

-- or -- ☒ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

CEN17LA105

Reviewed by NTSB Regional Office

CEN

Name of Investigator

LINDBERG

Date Report Received

4/10/17