

Date : 01/07/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000043-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1615.00
A/C TSN : 7477.70
Landings : 8429

- 5
PAGE

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Updated #1 GPS per Beech MM 3400. next due 02-04-2016. Ops check ok for return to service.

Date : 01/07/2016

Signature: [REDACTED]

Tech Log # : tl-000043-2016

Bryan Peters

A&P [REDACTED]

Printed by Ramco

Date : 01/18/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000081-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1641.50
A/C TSN : 7504.20
Landings : 8457

AIRFRAME ENTRIES

MXRD-000062-2016 MEL NEF 25-20-02 USB Ports In-op.
R&R Dual USB Charging Port Assembly IAW True Blue Power TA102 Series Installation Manual and Beechcraft King Air C90 Maintenance Manual. Operational check satisfactory. This action clears MEL NEF 25-20-02. Aircraft is approved for return to service.
Installed Part #: 6430102-4 ; Installed SN #: A15-11298 ; Removed Part #: 6430102-4 ; Removed Serial#: J14-11289;

Date : 01/18/2016

Signature: [REDACTED]

Tech Log # : TL-000081-2016

Aaron Cheney

A&P [REDACTED]

Printed by Ramco

Date : 01/21/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000091-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1647.80
A/C TSN : 7510.50
Landings : 8463

AIRFRAME ENTRIES

MXRD-000084-2016 MEL 33-40-04 Ref Log page 608222
Rear position light inop.
R&R Tail position light bulb IAW Beechcraft King Air C90 Maintenance Manual. Operational check satisfactory. This action clears MEL 33-40-04 and aircraft is approved for return to service.

Date : 01/21/2016

Signature: [REDACTED]

Tech Log # : TL-000091-2016

Aaron Cheney

A&P [REDACTED]

Printed by Ramco

Date : 01/30/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000123-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1667.60
A/C TSN : 7530.30
Landings : 8487

AIRFRAME ENTRIES

MXRD-000122-2016 Pressurization not making max diff.
Removed L/H Flow Pack P/N 97-380000-33 S/N 3042. Installed overhauled L/H Flow Pack P/N 97-380000-33 S/N 745. Ops checked good. Work done in reference to
Beech King Air 90 series MM
Installed Part #: 97-380000-33 ; Installed SN #: 745 ; Removed Part #: 97-380000-33 ; Removed Serial#: 3042;

I certify that this aircraft/engine/prop has been inspected IAW MFG current inspection program and was found to be in airworthy condition for the work performed.

Date : 01/30/2016

Signature: [Redacted]

Tech Log # : TL-000123-2016

Printed by Ramco

Stephen Weir

A&P [Redacted]

Date : 02/01/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000135-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1668.10
A/C TSN : 7530.80
Landings : 8488

AIRFRAME ENTRIES

MXRD-000128-2016 L/H fuel indicator drops 200-300 lbs in flight
R/R L/H matrix blocks. System checks good. IAW Beechcraft King Air 90 series MM

Date : 02/01/2016

Signature: [Redacted]

Tech Log # : TL-000135-2016

Printed by Ramco

Dan Palmer

A&P [Redacted]

Date : 02/03/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000155-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1670.20
A/C TSN : 7532.90
Landings : 8492

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Update Garmin GPS Nav Data card to the current cycle, 1602, expires March 3, 2016, IAW DGRW 72 and Garmin ICA for the 400/500.
99A9999-99 I certify that this aircraft/engine/prop has been inspected IAW MFG current inspection program and was determined to be in airworthy condition

Date : 02/03/2016

Signature: [Redacted]

Tech Log # : TL-000155-2016

Printed by Ramco

Kenneth
Sanderson

A&P [Redacted]

Date : 02/25/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000247-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1720.70
A/C TSN : 7583.40
Landings : 8569

7
PAGE

AIRFRAME ENTRIES

- MXRD-000240-2016 RDR doesn't work. Gives sensor fail message
R/R radar rcvr xmtr. Removed p/n 622 7337-001 s/n 2167. Install p/n 622-7337-001 s/n 1468. System checks good IAW Beechcraft King Air AMM.
Installed Part #: 622-7337-001 ; Installed SN #: 1468 ; Removed Part #: 622-7337-001 ; Removed Serial#: 2167;
- MXRD-000242-2016 L/H fuel quantity indicator reads incorrect
R/R leading edge outboard fuel probe. Removed p/n 100-380006-187 s/n 0277. Installed p/n 100-380006-187 s/n AAR0291. System checks good. IAW
Beechcraft King Air AMM.
Installed Part #: 100-380006-187 ; Installed SN #: AAR0291 ; Removed Part #: 100-380006-187 ; Removed Serial#: 0277;
- MXRD-000243-2016 R/H fuel quantity indicator reads incorrect.
R/R fuel quantity indicator, leading edge inboard fuel probe, and related terminal blocks. Removed indicator p/n 117-384019-3 s/n 9613-750. Installed indicator p/n
117-384019-3 s/n 0612-3993. Removed probe p/n 100-380006-175 s/n 0924-013M. Installed probe p/n 100-380006-175 s/n 0714-003M3. System checks good.
IAW Beechcraft King Air AMM.
Installed Part #: 117-384019-3 ; Installed SN #: 0612-3993 ; Removed Part #: 117-384019-3 ; Removed Serial#: 9613-750;
Installed Part #: 100-380006-175 ; Installed SN #: 0714-003M3 ; Removed Part #: 100-380006-175 ; Removed Serial#: 0924-013M;

Date : 02/25/2016

Signature

Dan Palmer

A&P

Tech Log # : tl-000247-2016

Printed by Ramco

Date : 03/02/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000247-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1721.30
A/C TSN : 7584.00
Landings : 8571

AIRFRAME ENTRIES

- MXRD-000243-2016 R/H fuel quantity indicator reads incorrect.
R/R fuel quantity indicator, leading edge inboard fuel probe, center fuel probe, outboard leading edge probe, nacelle fuel probe, and related terminal blocks.
Removed indicator p/n 117-384019-3 s/n 9613-750. Installed indicator p/n 117-384019-3 s/n 0612-3993. Removed probe p/n 100-380006-175 s/n 0924-013M.
Installed probe p/n 100-380006-175 s/n 0738-028M3 removed p/n 100-380006-183 s/n 1396 installed p/n 100-380006-183 s/n 0437 removed p/n 100-380006-187 s/n
0922-003M3 installed 100-380006-187 s/n 16B358 and removed p/n 100-380006-185 s/n unknown installed p/n 100-380006-185 s/n AAF1915M3. System checks
good. IAW Beechcraft King Air AMM.
Installed Part #: 117-384019-3 ; Installed SN #: 0612-3993 ; Removed Part #: 117-384019-3 ; Removed Serial#: 9613-750;
Installed Part #: 100-380006-175 ; Installed SN #: 0714-003M3 ; Removed Part #: 100-380006-175 ; Removed Serial#: 0924-013M;
Installed Part #: 100-380006-187 ; Installed SN #: 16B358 ; Removed Part #: 100-380006-187 ; Removed Serial#: 0922-003M3;
Installed Part #: 100-380006-183 ; Installed SN #: 0437 ; Removed Part #: 100-380006-183 ; Removed Serial#: 1396;
Installed Part #: 100-380006-175 ; Installed SN #: 0738-028M3 ; Removed Part #: 100-380006-175 ; Removed Serial#: 0924-013M;
Installed Part #: 100-380006-185 ; Installed SN #: AAF1915M3 ; Removed Part #: 100-380006-185 ; Removed Serial#: unknown;

Date : 03/02/2016

Signature

Dominic Mercer

A&P

Tech Log # : tl-000247-2016

Printed by Ramco

Date : 02/11/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000214-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1685.50
A/C TSN : 7548.20
Landings : 8518

AIRFRAME ENTRIES

MXRD-000197-2016 LH Rear Brake leaking.

Removed and cleaned LH brake assem. Found warped rotor disk w/abnormal pad wear. Replace wheel/tire assem., P/N 40-170A, S/N AS12903. Installed O/H'd tire/wheel assem, P/N 40-170A, S/N AS12270. Install Serviceable brake assembly, P/N 30-144, S/N 1865. Removed comp. P/N 30-144, S/N 1774. Bleed brake system as required and refill res.-No leaks noted. Work done IAW Beechcraft AMM ch 32 and Cleland ICA. AC ok for RTS.
Installed Part #: 40-170A ; Installed SN #: AS 12270 ; Removed Part #: 40-170A ; Removed Serial#: AS12903;

08A3240-02 Left Hand Cleveland MLG Brakes & Wheels ICA Ref. Manual 199-90

Removed existing per discrepancy listed and replaced with O/H'd unit.

99A9999-99 I certify that this aircraft/engine/prop has been inspected IAW MFG current inspection program and was determined to be in airworthy condition

Date : 02/11/2016

Signature: [Redacted]

Tech Log # : TL-000214-2016

Kenneth
Sanderson

A&P [Redacted]

Printed by Ramco

Date : 03/07/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000338-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1721.50
A/C TSN : 7584.20
Landings : 8572

AIRFRAME ENTRIES

08A3400-03 GPS Update #1

Complied with GNS 500W update cycle 1603 IAW Jeppesen instructions. Ops check normal. Next update due on 03/31/2016.

99A9999-99 I certify that this aircraft/engine/prop has been inspected IAW MFG current inspection program and was determined to be in airworthy condition

Date : 03/07/2016

Signature: [Redacted]

Tech Log # : TL-000338-2016

Ross Hausmann

A&P [Redacted]

Printed by Ramco

Beechcraft



Hawker

TEXTRON AVIATION

1980 Airport RD
Wichita KS 67209
Phone: (316)676-4500
Fax: (316)671-3729
FAA Certified Repair Station: BWVR672C
EASA Certified Repair Station: 145.5086

- 9
PAGE

AIRFRAME LOG ENTRY

MODEL	A/C S/N	A/C REG	W/O	AC TT	AC TCYC	HR MTR	DATE
C90A	LJ-1365	N1551C	ICT04001566	7586.1	8577	1723.4	3/29/2016

A. MAINTENANCE ACTIONS PERFORMED:

1. REPLACED TOTAL/NACELLE SELECT SWITCH P/N 7401TZQE WITH NEW SWITCH IAW MM 28-41-01 & WDM 28-01-03, 28-41-01 & 28-41-02.

FOR DETAILED DESCRIPTION OF ALL WORK PERFORMED, REFERENCE THE HAWKER BEECHCRAFT SERVICES WORK ORDER LISTED IN LOGBOOK ENTRY HEADER ABOVE.

"I CERTIFY THAT THIS AIRCRAFT WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH FAA REGULATIONS AND IS AIRWORTHY AND APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED ONLY."

Hawker Beechcraft Services
FAA Certified Repair Station: BWVR672C
EASA Certified Repair Station: 145.5086

Name: Glenn Lull
Title: Inspector

Date : 04/04/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000247-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1723.60
A/C TSN : 7586.30
Landings : 8578

AIRFRAME ENTRIES

MXRD-000390-2016 radar has ghost returns

Removed and replaced the radar unit. P/N 622-2501-001, S/N 3543 was removed, S/N 3606 was installed. Operational check is good. *Reference Collins install manual. ops check Ref. EASA Avionics manual.*

Date : 04/04/2016

Signature: [Redacted]

Tech Log # : tl-000247-2016

Ryan Muhsey

A&P [Redacted]

Printed by Ramco

Date : 04/04/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000453-2016

EagleMed LLC
6601 W Pueblo Dr.
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1723.60
A/C TSN : 7586.30
Landings : 8578

AIRFRAME ENTRIES

08A3400-03 GPS Update #1

Updated GNS 500 cycle 1604 IAW Jeppesen instructions. Ops check normal. Next update due 04/28/2016.

CMP0000-00 Remove Part for Mx

Removed main ship battery P/N RG380E/44K, S/N 40732724. Installed new battery P/N RG380E/44K, S/N 40788895. Ops check normal. All work performed IAW Beechcraft 90-series MM.

99A9999-99

I certify that this aircraft/engine/prop has been inspected IAW MFG current inspection program and was determined to be in airworthy condition

Date : 04/04/2016

Signature: [Redacted]

Tech Log # : tl-000453-2016

Ross Hausmann

A&P [Redacted]

Printed by Ramco

Date : 04/25/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech-Log # : TL-000534-2016

EagleMed LLC

6601 W Pueblo Dr.

Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1724.00

A/C TSN : 7586.70

Landings : 8581

AIRFRAME ENTRIES

MXRD-000520-2016

Remove and Replace RH engine starter generator.

Removed RH Engine starter generator p/n 23048-016 s/n 12359. Installed RH Engine starter generator p/n 23048-016 s/n 1092m. Ops Check Good. Work Done IAW Beech C-90 mm and P&W mm

08A8010-02

Start Gen QAD Flange Right

C/W Rh Start Gen QAD Flange Right insp. No Defects Noted. Work Done IAW Beech king air c90 mm and P&W mm.

Aircraft found to be approved for return to service for the work performed.

Date : 04/25/2016

Signature: [Redacted]

Tech Log # : TL-000534-2016

Brenden Swopes

A&P [Redacted]

Printed by Ramco

Date : 04/25/2016

EagleMed LLC

A/C Reg # : N1551C

6601 W Pueblo Dr.

Hobbs : 1724.00

Model # : C90A

Wichita, KS 67209

A/C TSN : 7586.70

Serial # : LJ-1365

Phone : (316) 613-4855

Landings : 8581

Manufacturer # : BEECHCRAFT

Tech Log # : TL-000479-2016

AIRFRAME ENTRIES

MXRD-000532-2016

RH fuel quantity reads low.

Removed and replaced all matrix block connectors on RH side, PN's M81714/2BC1(5) M81714/7-AB1(2) no fix. R&R RH fuel Quantity indicator PN on/off 117-384019-3 SN on 9801-1277 SN off 0612-3993 and connector(DA15S), no fix. Removed and replaced center section probe (100-380006-183) SN on AAR0101 SN off unreadable Swapped probes from RH to LH side, problem carried over to LH side. Removed and replaced all three OB wing probes PN 100-380006-173 SN on AAR1195M3 SN off AAR1079, 100-380006-175 SN on AAR0974 SN off unreadable, 100-380006-103 SN on 2002 SN off unreadable. Calibrated system. Ops check normal. All work done IAW Beech Kingair 90 MM. Aircraft is approved for return to service.

Date : 04/25/2016

Signature: [Redacted]

Tech Log # : TL-000479-2016

Curtis Murphy

A&P [Redacted]

Printed by Ramco

Date : 04/28/2016

EagleMed LLC

A/C Reg # : N1551C

6601 W Pueblo Dr.

A/C TSN : 7594.90

Model # : C90A

Wichita, KS 67209

Landings : 8595

Serial # : LJ-1365

Phone : (316) 613-4855

Manufacturer # : BEECHCRAFT

Tech Log # : TL-000568-2016

AIRFRAME ENTRIES

08A3400-03

GPS Update #1

Complied with GPS update in reference to Jeppesen Distribution Manager. Current cycle is 1605 expires May 26, 2016.

99A9999-99

The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service.

Date : 04/28/2016

Signature: [Redacted]

Tech Log # : TL-000568-2016

Ryan Long

A&P [Redacted]

Printed by Ramco

Date : 05/04/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000602-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1745.70
A/C TSN : 7608.40
Landings : 8608

- 11
PAGE

AIRFRAME ENTRIES

MXRD-000586-2016 Upper CRT Effis tube blurry.
Removed pilot side upper electronic flight display P/N 622-9681-001, S/N 760. Installed repaired electronic flight display P/N 622-9681-001, S/N HBNK IAW
Beechcraft 90-series MM. Ops check normal.

Date : 05/04/2016

Signature: [Redacted]

Ross Hausmann

A&P [Redacted]

Tech Log #: tl-000602-2016

Printed by Ramco

Date : 05/04/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000602-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1745.70
A/C TSN : 7608.40
Landings : 8608

AIRFRAME ENTRIES

MXRD-000591-2016 Lowest horizontal pitch bar indication of the attitude indicator on the upper Effis CRT only shows as a blinking white dot.
Removed DPU P/N 622-9682-004, S/N 3KLH. Installed inspected and tested DPU P/N 622-9682-004, S/N 10FVF IAW Beechcraft 90-series MM. Ops check normal.

Date : 05/04/2016

Signature: [Redacted]

Ross Hausmann

A&P [Redacted]

Tech Log #: tl-000602-2016

Printed by Ramco

Date : 05/05/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000611-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1747.30
A/C TSN : 7610.00
Landings : 8610

AIRFRAME ENTRIES

MXRD-000601-2016 Effis screen showed a DPU Fail. Message.
Removed and replaced DPU-84, with inspected and tested unit. Ops check good. Work done IAW Beech Kingair 90 MM. Aircraft approved for return to service.
Installed Part #: 622-9682-004; Installed SN #: 887; Removed Part #: 622-9682-004; Removed Serial#: 10FVF;

Date : 05/05/2016

Signature: [Redacted]

Curtis Murphy

A&P [Redacted]

Tech Log #: TL-000611-2016

Printed by Ramco

Date : 05/12/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000656-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1754.60
A/C TSN : 7617.30
Landings : 8622

AIRFRAME ENTRIES

MXRD-000664-2016 Pilots EFD-84 screen looks to be deteriorating.
Removed and replaced EFD-84 screen, with repaired. PN on/off 622-9681-001 SN on H5GP SN off HBK. Ops check good. Work done IAW Beech Kingair 90 MM.
Aircraft is approved for return to service.
Installed Part #: 622-9681-001 ; Installed SN #: H5GP ; Removed Part #: 622-9681-001 ; Removed Serial#: HBK;

Date : 05/12/2016

Signature

Curtis Murphy

A&P

Tech Log #: TL-000656-2016

Printed by Ramco

Date : 05/26/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000721-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1776.40
A/C TSN : 7639.10
Landings : 8650

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Complied with GPS update in reference to Jeppesen Distribution Manager. Current cycle 1606 and expires 6/23/16.
99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 05/26/2016

Signature

Ryan Long

A&P

Tech Log #: TL-000721-2016

Printed by Ramco

Date : 05/18/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000692-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1764.10
A/C TSN : 7626.80
Landings : 8633

AIRFRAME ENTRIES

MXRD-000708-2016 Threshold entry light lens is broken.
Removed and replaced threshold entry light lens per Beech King Air C90 M/M 3320. Ops check ok for return to service.

Date : 05/18/2016

Signature

Bryan Peters

A&P

Tech Log #: tl-000692-2016

Printed by Ramco

Date : 05/18/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000686-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1764.10
A/C TSN : 7626.80
Landings : 8633

- 13
PAGE

AIRFRAME ENTRIES

MXRD-000697-2016 LH boost pump inop on hot battery buss.
Removed and replaced both buss fuses for the LH boost pump per Beech King Air C90 M/M 2430. Ops check ok for return to service.

Date : 05/18/2016

Signature: [Redacted]

Bryan Peters

A&P [Redacted]

Tech Log #: tl-000686-2016

Printed by Ramco

Date : 05/18/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000693-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1764.10
A/C TSN : 7626.80
Landings : 8633

AIRFRAME ENTRIES

MXRD-000709-2016 Bird strike on LH INB wing.
Insp. LH INB leading edge and wing, found remains in heat exchanger and duct, cleaned area. Insp. LH Eng. for ingestion, found none. Ops check ok for return to service.

Date : 05/18/2016

Signature: [Redacted]

Bryan Peters

A&P [Redacted]

Tech Log #: tl-000693-2016

Date : 06/03/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000766-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1787.20
A/C TSN : 7649.90
Landings : 8666

AIRFRAME ENTRIES

MXRD-000766-2016 Seat belt sign light inop.
Removed and replaced graphic sign assembly with new assembly, completed ops checks, no defects noted.

MXRD-000767-2016 Logo light on RH horizontal is inop.
Removed and replaced R/H logo light bulb with new bulb, completed ops checks, no defects noted. P/N 34-0228070-67

MXRD-000768-2016 Altitude alerter glass is loose.
Removed and replaced altitude alerter with overhauled unit, completed ops checks, no defects noted.
Installed Part #: 45100-D4010 ; Installed SN #: 1051 ; Removed Part #: 45100-D4010 ; Removed Serial#: 913;

MXRD-000787-2016 - Co-pilot attitude indicator lighting inop.
Repositioned post light to cover more, completed ops checks, no defects noted.

MXRD-000788-2016 Lower R/H subpanel lighting inop.
Cleaned light socket, completed ops checks, no defects noted.

MXRD-000789-2016
All work done IAW Beech C90 MM and Aircraft is approved for return to service.

Date : 06/03/2016

Signature: [Redacted]

William Shelton

A&P [Redacted]

Tech Log #: TL-000766-2016

Printed by Ramco

Date : 06/17/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : tl-000795-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1806.90

A/C TSN : 7669.60

Landings : 8686

AIRFRAME ENTRIES

08A510-01 Phase 1

C/W Phase 1 inspection. Work done in reference to Beech King Air 90 series MM.

08A6300-01 Raisbeck Strake inspection ICA Ref Manual 85-120 Section 53-00-00-05

C/W Raisbeck Strake Inspection. No defects noted. Work done in reference to Raisbeck Engineering ICA Doc. 85-120.

08A3240-04 Right Hand Cleveland MLG Brakes & Wheels ICA Ref. Manual 199-90

Complied with Right Hand Cleveland MLG Brakes & Wheels ICA. All work done in reference with Cleveland Wheels and Brakes MM and King Air 90 AMM.

08A1220-01 200 Hour Lubrication

C/W 200 Hour Lubes. Work done in reference to Beech King Air 90 series MM.

08A3240-01 Cleveland Nose Wheel ICA Ref. CMM 040-20400

C/W Cleveland Nose Wheel ICA. No defects noted. Work done in reference to Cleveland Brakes and Wheels Nose Wheel ICA.

CMP3500-01 Oxygen Bottle Assembly 3 year Hydro Test

Removed ship O2 bottle/Regulator Assy P/N 801293-06 S/N ST5951/7195 to send out for 3 year hydro/overhaul. Installed a Serviceable, Hydrostatic tested bottle/regulator assy to the Aircraft. PN on 801293-06, SN on C14049769. Serviced with 1700 PSI of O2, No leaks noted, Ops check Normal. Next Hydro Due JUN 2019. Maintenance IAW Beechcraft 90 Series MM.

CMP3500-02 Oxygen Bottle Assembly - 21 year Service Life Limit

08A3240-02 Left Hand Cleveland MLG Brakes & Wheels ICA Ref. Manual 199-90

Complied with Left Hand Cleveland MLG Brakes & Wheels ICA. All work done in reference with Cleveland Wheels and Brakes MM and King Air 90 AMM.

08A5310-01 Fuselage Structure Inspection Ref. AMM 53-10-00

C/W Fuselage Structure Insp. IAW 53-10-00. No defects found.

08A5730-01 BLR Winglets

Complied with BLR Winglets. All work done in reference with BLR Performance Innovation, Document BLR-KA90W-950, Instructions for Continued Airworthiness - King Air C90A, C90GT and C90GTI Winglet System. FAA STC NO : SA02054SE. No defects noted at this time.

08A1220-05 Upper Wing Bolts Barrel Nuts Lubrication - Ref. AMM 12-20-11-301 Item I-8

C/W Upper Wing Bolts Barrel Nuts Lubrication IAW AMM 12-20-11-301 Item I-8. No defects noted.

08A5700-06 Upper & Lower Outboard Wing Panel Main Spar Visual Inspection Ref SIRM Chapter 57-13-02-201 Fig. 204

C/W visual inspection of upr & lwr O/B wing panel main spar IAW SIRM Ch 57. No defects noted.

08A3310-02 Pilot Fuel Control Edgelighted Panel Ref. AMM 33-10-01-601

C/W Pilots Fuel Control Edgelighted Panel Inspection. Replaced burned out lamps as needed. Work done in reference to Beech King Air 90 series MM.

08A2560-01 FAR 91.207(d) ELT Annual Inspection

C/W FAR 91.207(d) ELT Annual Inspection. No defects noted. Work done in reference to FAR 91.207(d) and Artex ME406 Doc 570-1600

08A2130-01 Cabin Altitude Warning System Check Ref. AMM 21-30-11-501 Method 3.

Complied with cabin altitude pressure warning system check IAW Beechcraft 90-series MM. Ops check normal. No defects noted.

08A3200-01 Brake System Hoses (exposed)

Complied with exposed hydraulic brake hose replacement. IAW Beech King Air 90 MM.

MXRD-000838-2016 Change old style hydraulic brake reservoir to new style.


Removed old hydraulic brake reservoir P/N 50-580039-11. Installed new style hydraulic brake reservoir P/N 101-580298-601. Filled and bled system, leak checked good. Work done in reference to Beech King Air 90 series MM

99A9999-99 The Inspection(s) and or Maintenance identified above, was determined to be in airworthy condition and approved for return to service

Date : 06/17/2016

Signature: 

Curtis Murphy

A&P 

Tech Log #: tl-000795-2016

Printed by Ramco

Date : 06/17/2016
A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : TL-000795-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1000.00
A/C TSN : 7669.60
Landings : 8386

15
PAGE

AIRFRAME ENTRIES

MXRD-000871-2016 Maintenance requests post maintenance operational acceptance test flight.
Test flight satisfactory. No defects noted. This aircraft is approved for return for service.

Date : 06/17/2016

Signature: [Redacted]

Lic. Type Cert [Redacted] ATP

Tech Log # : tl-000795-2016

Printed by Ramco

Date : 06/22/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : TL-000846-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1810.70

A/C TSN : 7673.40

Landings : 8689

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Updated GPS NAV DATA card for the Garmin 500 to current cycle #1607. Expires 21 July 2016.

Date : 06/22/2016

Signature: [Redacted]

Steve Philippart

A&P [Redacted]

Tech Log # : TL-000846-2016

Printed by Ramco

Date : 07/30/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : TL-001015-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1822.60

A/C TSN : 7685.30

Landings : 8700

AIRFRAME ENTRIES

08A3400-03 GPS Update #1

UPDATED GPS AS REQUIRED

99A0000-00

Compulsory Maintenance Check Required for...

COMPULSORY MAINTENANCE CHECK REQUIRED FOR REMOVAL OF ALL FLIGHT CONTROLS DUE TO PAINT AND WEIGHT AND BALANCE.
TEST FLIGHT SATISFACTORY. SIGNED BY PILOT DARIE. PADRON 3310714

99A9999-99

The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

MXRD-001071-2016

AIRCRAFT DUE NEW PAINT

PAINT AIRCRAFT, COMPLIED BY VALAIR CRS# V5SR2173 DETAILS OF WORK PERFORMED ARE ON FILE AT VALAIR UNDER WO# 1515, 1535, 1553, AND 1558

Date : 07/30/2016

Signature: [Redacted]

Ricardo Moreno

A&P [Redacted]

Tech Log # : TL-001015-2016

Printed by Ramco

Date : 08/01/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001017-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1827.40
A/C TSN : 7690.10
Landings : 8703

AIRFRAME ENTRIES

MXRD-001073-2016 LEFT ENGINE NOT DEVELOPING MIN TAKEOFF TORQUE PER MIN TAKEOFF POWER CHART
CONFIRMED DISCREPANCY, FOUND P3 LEAK, REMOVED AND RELACED L/H ENGINE P3 LINE COMPRESSOR SECTION ADAPTER'S GASKET AND TH P3
LINE FLANGE GASKET, ~~ENGINE PRODUCED~~ 180 TORQUE, ITT 690 C, TURBINE 98.1, FUEL FLOW 370 lbs, AND ROP RPM 2200 LEAK AND OPS CHECK
GOOD.
P/ 97-91001-1
P/N 303993

Date : 08/01/2016

Signature:

Ricardo Moreno

A&P

Tech Log # : TL-001017-2016

Printed by Ramco



ValairAviation

AGC AEROSPACE & DEFENSE

FAA Certified Repair Station #V5SR2170
7301 N.W. 50th Street Oklahoma City, Oklahoma 73132-9702
Phone: 405.789.5000 Fax: 405.789.5995

Airframe Log Entry

N1551C	Beechcraft C90A	AC S/N - LJ-1365	July 30, 2016
ACTT:	7,685.3	ACTC:	8,700
		Hourmeter:	1,822.6

Performed the following Non-Routine Maintenance Items:

Aircraft was stripped, prepped & painted in accordance with Valair Aviation FAA approved, Process Spec, #100, using the following colors: Base Color: Matterhorn White, #570-535, Black #571-900, Stripe Colors: Firecracker Red #WO5963. All primary flight controls were balance checked after paint and before reinstallation on the aircraft in accordance with the instructions and procedures contained in the Beech C90 Maintenance Manual. All required exterior placards were installed at this time.

Installed 8 (ea) new flap bearings, p/n - A-11540 and 8 (ea) new flange rollers assys, p/n - A11538.

Painted Props.

Installed new elevator bellcrank rig pin hole channel assy, p/n - 50-440031-21.

Performed elevator control system inspection with rigging check.

Performed rudder rigging check.

Weighed aircraft, see W&B section in POH for current weight and balance.

Performed the following Major Alterations:

Installed Life Port Bed with reference STC# SA01213CH. See FAA form 337 dated 07/29/16 for complete details of the work performed.

The aircraft was weighed after all the above work was completed; a new revised Weight and Balance Sheet was inserted in the AFM, Weight & Balance Section.

All work was done in accordance with the applicable sections of the PT6A-21 Maintenance Manual, the Hartzell Propeller Maintenance Manual, and the Beechcraft C90 Maintenance Manual.

The maintenance described above is certified Airworthy, and with respect to the work performed this aircraft is approved for return to service.

Details are on file at this facility under WO-1515, 1535, 1553, 1558.

Glen Williams for CRS# V5SR2170

Date : 08/09/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001044-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1835.90
A/C TSN : 7698.60
Landings : 8712

- 17
PAGE

AIRFRAME ENTRIES

MXRD-001105-2016 R/H MLG TIRE IS WORN
REMOVED AND REPLACED R/H MLG WHEEL ASSYN IAW C90 M/M 32-40-00-201, SERVICED TIRE PRESSURE TO 70 PSI, LEAK AND OPS CHECK GOOD.
P/N OFF 40-170A S/N 002, P/N ON 40-170A S/N ASI2255
Installed Part #: 40-170A ; Installed SN #: ASI2255 ; Remove Part #: 40-170A ; Removed Serial#: 002;

Date : 08/09/2016

Signature: [REDACTED]

Ricardo Moreno

A&P [REDACTED]

Tech Log #: TL-001044-2016

Printed by Ramco

Date : 09/09/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001179-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1859.10
A/C TSN : 7721.80
Landings : 8742

AIRFRAME ENTRIES

CMP0000-00 Remove Part for Mx
LH engine has bolt and extractor seized in upper fwd bolt hole of bleed air flange. Removed engine P/N PT6A-21, S/N PCE-25774. Times and Cycles at time of removal; TT 7707.40 TSO: 4155.9 CSN: 8719 CSO: 5051 Installed engine P/N PT6A-21, S/N PCE-25741 in the #1 location. Times and Cycles at time of installation; TT: 13922.4 TSO: 188.9 CSN: 18270 CSO: 282. Rigged engine. Ops and leak checks good. All work performed IAW Beechcraft 90-series MM and P&W PT6A-21 MM.

99A0000-00 Compulsory Maintenance Check Required for...

Compulsory maintenance check performed for the removal and replacement of the RH engine. Compulsory maintenance check accomplished by Gerald Archuleta [REDACTED] A&P [REDACTED]

99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 09/09/2016

Signature: [REDACTED]

Ross Hausmann

A&P [REDACTED]

Tech Log #: tl-001179-2016

Printed by Ramco

Date : 09/12/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001179-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1860.20
A/C TSN : 7722.90
Landings : 8745

AIRFRAME ENTRIES

MXRD-001282-2016 Install Lifeport medical spectrum.
Removed Spectrum Aeromed spectrum. Installed new Lifeport medical spectrum. Ops checks normal. All work performed IAW Lifeport MM and Spectrum Aeromed MM. Reference 337 dated 07/29/2016.

99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 09/12/2016

Signature: [REDACTED]

Ross Hausmann

A&P [REDACTED]

Tech Log #: tl-001179-2016

Printed by Ramco

Date : 09/12/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001179-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1860.20
A/C TSN : 7722.90
Landings : 8745

AIRFRAME ENTRIES

MXRD-001276-2016 RH main landing gear actuator leaking hydraulic fluid.
Removed RH main landing gear hydraulic actuator P/N 90-388000-1, S/N 1unreadable. Installed overhauled MLG actuator assembly P/N 90-388000-1, S/N 121. Performed landing gear swings and rig check. Ops and rig check good. All work done IAW Beechcraft 90-series MM.
MXRD-001277-2016 Aircraft flutters in pitch when making turns in heading mode.
Removed elevator trim tab actuator P/N 109-524329-1, S/N 2unreadable. Installed repaired electric elevator trim tab actuator P/N 109-524329-1. Rigged elevator and elevator trim tab system. Ops and rig check good. All work performed IAW Beechcraft 90-series MM.
MXRD-001281-2016 LH strobe light inop.
Removed and replaced LH flash tube assy, with new. Ops check good. Work done IAW Beech King Air 90MM.
99A9999-99 The inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 09/12/2016

Signature: [Redacted]

Ross Hausmann

A&P [Redacted]

Tech Log # : tl-001179-2016

Printed by Ramco

Date : 09/09/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001179-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1859.10
A/C TSN : 7721.80
Landings : 8742

AIRFRAME ENTRIES

MXRD-001269-2016 Maintenance requests post maintenance operational acceptance test flight.
Test flight satisfactory. No defects noted. This aircraft is approved for return to service.

Date : 09/09/2016

Signature: [Redacted]

Lic. Type Cert

Tech Log # : tl-001179-2016

Printed by Ramco

Date : 09/14/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001200-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1863.40
A/C TSN : 7726.10
Landings : 8746

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Updated GPS Nav Data Card for the GNS 500W to current cycle #1609. Expires 13 Oct 2016.

Date : 09/14/2016

Signature: [Redacted]

Steve Philippart

A&P [Redacted]

Tech Log # : TL-001200-2016

Printed by Ramco

Date : 09/16/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001225-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1866.00
A/C TSN : 7728.70
Landings : 8749

- 19
PAGE

AIRFRAME ENTRIES

MXRD-001300-2016 I H strobe inop
Replaced left wing strobe light bulb P/N 01-0790028-01, IAW C90B MM, checks good, AC ok for RTS.

Date : 09/16/2016

Signature:

Steve Philippart

A&P

Tech Log #: TL-001225-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1879.60

A/C TSN : 7742.30

Landings : 8764

100

Date : 09/22/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001241-2016

AIRFRAME ENTRIES

KRD-001317-2016 Pilots DG off 5-10 degrees.
Adjusted Lt and Rt wing flux valves IAW C90B MM, ground checks good. AC ok for RTS.

Date : 09/22/2016

Signature:

Steve Philippart

A&P

Tech Log #: TL-001241-2016

Printed by Ramco

Date : 10/05/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001286-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1895.70

A/C TSN : 7758.40

Landings : 8782

AIRFRAME ENTRIES

NST-000014-2016 Weather radar spoking during operation.
Replaced weather radar antenna with overhauled unit P/N 622-2501-001, S/N 3809. IAW C90B MM. Ground checks good. AC ok for RTS.
Installed Part #: 622-2501-001 ; Installed SN #: 3809 ; Removed Part #: 622-2501-001 ; Removed Serial#: 3606;

Date : 10/05/2016

Signature:

Steve Philippart

A&P

Tech Log #: TL-001286-2016

Printed by Ramco

Date : 10/05/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : TL-001283-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1895.70

A/C TSN : 7758.40

Landings : 8782

AIRFRAME ENTRIES

MXRD-001379-2016 A/C compressor seized up.
Replaced A/C system belts P/N 100-384112-1, compressor P/N 100-555059-1 and receiver/dryer P/N 90-384019-3, serviced A/C system IAW C90B MM. Ground checks good. AC ok for RTS.
Installed Part #: 100-555059-1 ; Installed SN #: 736B87 ; Removed Part #: SD-507 ; Removed Serial#: 2124307080;
08A2150-01 Air Cond. Compressor Drive Belt Tension Check - Ref. AMM 21-50-00
Complied with Air Cond. compressor drive belt tension check IAW C90B MM. AC ok for RTS.

Date : 10/05/2016

Signature: [Redacted]

Steve Philippart

A&P [Redacted]

Tech Log #: TL-001283-2016

Printed by Ramo

Date : 10/10/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : TL-001295-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1910.40

A/C TSN : 7773.10

Landings : 8793

AIRFRAME ENTRIES

NST-000016-2016 Air conditioning current limiter blown
Replaced limiter with a new ANL-M200 current limiter. System checks good, IAW C90B MM. Aircraft ok for Return To Service.
NST-000017-2016 Right logo light inop.
Replaced right logo light bulb, IAW C90B MM, checks good. Aircraft ok for Return To Service.
NST-000018-2016 Cockpit overhead light inop.
Replaced cockpit overhead light rheostat P/N CM42873 IAW C90B MM. Checks good. Aircraft ok for Return To Service.

Date : 10/10/2016

Signature: [Redacted]

Steve Philippart

A&P [Redacted]

Tech Log #: TL-001295-2016

Printed by Ramco

Date : 09/28/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001259-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1883.10
A/C TSN : 7745.80
Landings : 8770

OOK - 21
PAGE

FRAME ENTRIES

RD-001345-2016 Left engine leaking oil onto flaps
and engine fuel control fuel pump garlock seal leaking. Replaced seal P/N 3022375 and snap ring P/N AS3210-128 IAW P&W P16 21 MM. Ground checks good.
ok for RTS.

RD-001346-2016 Left main tire worn.
placed Left main wheel and tire assy with overhauled unit P/N 40-170A, IAW C90B MM, serviced tire with nitrogen. AC ok for RTS.
taller Part #: 40-170A ; Installed SN #: 050114-1 ; Removed Part #: 40-170A ; Removed Serial#: AS12270;

RD-001347-2016 Left and right logo lights inop.
placed bulb P/N A708-28, IAW C90B MM, checks good. AC ok for RTS.

RD-001348-2016 Left engine flow pack air duct deteriorated.
placed left engine flow pack duct P/N CEETS6-81-5 IAW C90B MM. AC ok for RTS.

Date : 09/28/2016 Signature: [Redacted] Tech Log # : TL-001259-2016
Steve Philippart A&P Printed by Ramco

Date : 10/11/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001299-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1910.40
A/C TSN : 7773.10
Landings : 8793

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Updated GPS NAV DATA card for the Garmin 500W to current cycle #1611. Expires 10 Nov 2016.

Date : 10/11/2016 Signature: [Redacted] Tech Log # : TL-001299-2016
Steve Philippart A&P Printed by Ramco

Date : 10/13/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001312-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1914.20
A/C TSN : 7776.90
Landings : 8797

AIRFRAME ENTRIES

MXRD-001408-2016 Right wing fuel quantity indicator reads 300 lbs low intermittently.
Replaced right wing leading edge fuel cell matrix connectors IAW C90B MM, checks good. Aircraft ok for Return To Service.

Date : 10/13/2016 Signature: [Redacted] Tech Log # : TL-001312-2016
Steve Philippart A&P Printed by Ramco

Date : 10/23/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001344-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1927.70
A/C TSN : 7790.40
Landings : 8808

AIRFRAME ENTRIES

MXRD-001466-2016 Left engine leaking oil from fuel control fuel pump garlock seal
Replaced left engine fuel control fuel pump garlock seal P/N 3022375 and o ring P/N AS3209-029 IAW P&W PT6-21 MM. ground ran, leak checked, checks good.
Aircraft ok for Return To Service.

Date : 10/23/2016

Signature:

Steve Philippart

Tech Log #: TL-001344-2016

Printed by Ramco

Date : 10/25/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001348-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1930.90
A/C TSN : 7793.60
Landings : 8811

AIRFRAME ENTRIES

08A3410-02 Avidyne FlightMax 12 Month ICA Ref. Manual AVMFD-083 Section 5
Complied with Avidyne Flightmax 12 month ICA, IAW Avidyne Flightmax ICA insp. guide, no discrepancies noted. Aircraft is ok for Return To Service.
08A3410-03 Garmin GNS 500W ICA Ref. Manual 190-00357
Complied with Garmin GNS 500W ICA IAW Garmin ICA Manual 90-00357, no discrepancies noted. Aircraft ok for Return To Service.

Date : 10/25/2016

Signature:

Steve Philippart

Tech Log #: TL-001348-2016

Printed by Ramco

Date : 10/26/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001352-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1930.90
A/C TSN : 7793.60
Landings : 8811

AIRFRAME ENTRIES

MXRD-001477-2016 Pilots control wheel clock lighting not working on left half of clock.
Replaced pilots control wheel clock with new unit P/N MB801-28 S/N 09187 IAW C90B MM checks good, aircraft ok for Return To Service.
Installed Part #: MB801-28 ; Installed SN #: 09187 ; Removed Part #: MB801-28 ; Removed Serial#: 01432;

Date : 10/26/2016

Signature:

Steve Philippart

Tech Log #: TL-001352-2016

Printed by Ramco

Date : 10/27/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001357-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1930.90
A/C TSN : 7793.60
Landings : 8811

- 23
PAGE

AIRFRAME ENTRIES

MXRD-001481-2016 Left engine smoking on shutdown
Replaced 2 101-309011-65 check valves on left engine EPA system, IAW C90B MM, checks good, aircraft ok for Return To Service.
MXRD-001482-2016 #1 Comm radio head goes blank Intermittently.
Replaced #1 Comm control head with repaired unit P/N 622-6520-008, S/N 18016 IAW C90B MM. Checks good, aircraft ok for Return To Service.
Installed Part #: 622-6520-000 ; Installed SN #: 18016 ; Removed Part #: 622-6520-008 ; Removed Serial#: 8868;

Date : 10/27/2016 Signature: [Redacted] Tech Log #: TL-001357-2016
Steve Philippart A&P [Redacted] Printed by Ramco

Date : 10/28/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001362-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1936.70
A/C TSN : 7799.40
Landings : 8816

AIRFRAME ENTRIES

08A2150-01 Air Cond. Compressor Drive Belt Tension Check - Ref. AMM 21-50-00
Complied with Air Cond. compressor drive belt tension check IAW C90B MM, adjusted as needed, checks good.
99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service
The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 10/28/2016 Signature: [Redacted] Tech Log #: TL-001362-2016
Steve Philippart A&P [Redacted] Printed by Ramco

Date : 11/07/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001397-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1953.70
A/C TSN : 7816.40
Landings : 8835

AIRFRAME ENTRIES

A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service
The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service
A2520-09 Lifeport ICA 100 Hour / Annual Inspection Ref. Manual EGR-677-12 Chapter 5
Complied with Lifeport 100 hour/ Annual insp. IAW Lifeport Insp. guide. No discrepancies noted.
A2520-08 Lifeport First 100 Hours Inspection Ref. Manual EGR-677-12 Chapter 5
Complied with Lifeport First 100 hour insp IAW Lifeport Insp. Guide. No discrepancies noted.

Date : 11/07/2016 Signature: [Redacted] Tech Log #: TL-001397-2016
Steve Philippart A&P [Redacted] Printed by Ramco

Date : 11/11/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001433-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1956.80
A/C TSN : 7819.50
Landings : 8836

AIRFRAME ENTRIES

MXRD-001571-2016 Cabin auto temp controller fan is inop
Removed old cabin auto temp controller P/N HYLZ 50336-1 S/N 2872J. Installed overhauled cabin auto temp controller P/N HYLZ 50336-1 S/N 4652K. Ops checked good. Work done in reference to Beech King Air 90 series MM.
Installed Part #: HYLZ50336-1 ; Installed SN #: 4652K ; Removed Part #: HYLZ50336-1 ; Removed Serial#: 2872J;
99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 11/11/2016

Signature: [REDACTED]

Tech Log #: tl-001433-2016

Stephen Weir

A&P [REDACTED]

Printed by Ramco

Date : 11/11/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001441-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1956.80
A/C TSN : 7819.50
Landings : 8836

AIRFRAME ENTRIES

MXRD-001573-2016 Remove Lifeport med bed and install Spectrum med bed.
Removed Lifeport med bed and installed Spectrum med bed ref. Spectrum manual 6011 and 337 dated 12 April 2012. Med bed is operational and A/C is approved for Return to Service.

Date : 11/11/2016

Signature: [REDACTED]

Tech Log #: tl-001441-2016

Duan Munsey

A&P [REDACTED]

Printed by Ramco

Date : 11/18/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001433-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1965.10
A/C TSN : 7827.80
Landings : 8846

AIRFRAME ENTRIES

MXRD-001567-2016 Air condition control in auto and manual INOP.
R/R CR193 and CR195 P/N 100-361045-11. R/R K4 and K5 P/N 50-380048-11. System checks good IAW King Air 90 AMM.
MXRD-001571-2016 Cabin auto temp controller fan is inop
Removed old cabin auto temp controller P/N HYLZ 50336-1 S/N 2872J. Installed overhauled cabin auto temp controller P/N HYLZ 50336-1 S/N 4652K. Ops checked good. Work done in reference to Beech King Air 90 series MM.
Installed Part #: HYLZ50336-1 ; Installed SN #: 4652K ; Removed Part #: HYLZ50336-1 ; Removed Serial#: 2872J;
MXRD-001572-2016 Air conditioning system does not come on in Auto mode. Works in Manual mode.
R/R CR193 and CR195 P/N 100-361045-11. R/R K4 and K5 P/N 50-380048-11. System checks good IAW King Air 90 AMM.

Date : 11/18/2016

Signature: [REDACTED]

Tech Log #: TL-001433-2016

Dan Palmer

A&P [REDACTED]

Printed by Ramco

Date : 11/08/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001412-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1953.70
A/C TSN : 7816.40
Landings : 8835

- 25
PAGE

AIRFRAME ENTRIES

MXRD-001532-2016 RT. Fuel Quantity Reads Low
Cleaned fuel panel connections. IAW C90B MM, checks good. This action clears MEL 28-41-05 REF Log page 602944. Ac ok for Return to service

Date : 11/08/2016 Signature: [Redacted] Tech Log #: TL-001412-2016
Steve Philippart A&P [Redacted] Printed by Ramco

Date : 11/09/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001414-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1953.70
A/C TSN : 7816.40
Landings : 8835

AIRFRAME ENTRIES

MXRD-001533-2016 Surface De-ice system inop.
Replaced surface de-ice distributor valve P/N 1532-3C with overhauled unit, IAW C90B MM, ground checks good, this action clears MEL 30-10-01, Ref. log page 602944. AC OK for Return To Service.
Installed Part #: 101-384144-1 ; Installed SN #: 19440-U ; Removed Part #: 1532-3C ; Removed Serial#: 42154-U;

Date : 11/09/2016 Signature: [Redacted] Tech Log #: TL-001414-2016
Steve Philippart A&P [Redacted] Printed by Ramco

Date : 11/10/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001422-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1953.70
A/C TSN : 7816.40
Landings : 8835

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Updated GPS NAV DATA card for the Garmin 500W to current cycle #1612. Expires 8 DEC 2016.

Date : 11/10/2016 Signature: [Redacted] Tech Log #: TL-001422-2016
Steve Philippart A&P [Redacted] Printed by Ramco

Date : 11/22/2016
A/C Reg #: N1551C
Model #: C90A
Serial #: LJ 1365
Manufacturer #: BEECHCRAFT
Tech Log #: tl-001439-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1965.50
A/C TSN : 7828.20
Landings : 8847

AIRFRAME ENTRIES

MXRD-001623-2016 Maintenance request post maintenance test flight.
Test flight satisfactory. No defects noted. This aircraft is approved for return to service.

Date : 11/22/2016

Signature: [REDACTED]

Lic. Type Cert [REDACTED]

Tech Log #: tl-001439-2016

Printed by Ramco

Date : 11/22/2016
A/C Reg #: N1551C
Model #: C90A
Serial #: LJ-1365
Manufacturer #: BEECHCRAFT
Tech Log #: tl-001439-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1965.10
A/C TSN : 7827.80
Landings : 8846

AIRFRAME ENTRIES

MXRD-001622-2016 Remove and replace LH engine.
Removed engine P/N PT6A-21 S/N PCE-25471 in serviceable condition. Times and cycles at time of removal; TT: 14028.4 TSO: 294.9 CSN: 18374 CSO: 386
Installed engine P/N PT6A-21, S/N PCE-25774 in the #1 location. Times and cycles at time of install; TT: 7707.4 TSO: 4155.9 CSN: 8719 CSO: 5051 Rigged engine. Performed engine performance runs. Ops and leak checks good. All work performed IAW P&W PT6A-21 MM and Beechcraft 90-series MM.

MXRD-001600-2016 Install medical O2 bottle P/N 3AL2216, S/N MM188699 in medical spectrum.
Installed medical O2 bottle P/N 3AL2216, S/N MM188699 in the medical spectrum. Serviced O2 and adjusted output regulator to supply 50 PSI. Ops and leak checks good. All work performed IAW Spectrum Aeromed MM.
Installed Part #: PT6A-21 ; Installed SN #: PCE-25774 ; Removed Part #: PT6A-21 ; Removed Serial#: PCE-25741; Position Code: ENGINE 1

99A9999-99

The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 11/22/2016

Signature: [REDACTED]

Ross Hausmann

A&P [REDACTED]

Tech Log #: tl-001439-2016

Printed by Ramco

Date : 11/28/2016
A/C Reg #: N1551C
Model #: C90A
Serial #: LJ-1365
Manufacturer #: BEECHCRAFT
Tech Log #: tl-001510-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1967.40
A/C TSN : 7830.10
Landings : 2849

AIRFRAME ENTRIES

MXRD-001664-2016 LH Outboard flap is dented at the trailing edge.
Removed and replaced the LH Outboard flap assy with a Serviceable assy. PN off 35-165050-218, SN off LJ-1365. PN on 35-165050-218, SN on LJ-1000. Checked rigging, MOC normal. Maintenance IAW Beech 90 Series MM.

Date : 11/28/2016

Signature: [REDACTED]

Jordan Pemberton

A&P [REDACTED]

Tech Log #: tl-001510-2016

Printed by Ramco

Date : 12/08/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001563-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1997.90
A/C TSN : 7860.60
Landings : 8882

- 27
PAGE

AIRFRAME ENTRIES

MXRD-001737-2016 Maintenance requests post maintenance operational acceptance test flight.
Test flight satisfactory. No defects noted. This aircraft is approved for return to service.

Date : 12/08/2016

Signature: [REDACTED]

Tech Log #: TL-001563-2016

Date : 12/07/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001548-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1993.50
A/C TSN : 7856.20
Landings : 8875

Printed by Ramco

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
I certify that the Garmin GPS card was updated accordingly for the Garmin 500, next due 1/5/2016.

Date : 12/07/2016

Signature: [REDACTED]

Tech Log #: TL-001548-2016

William Shelton

A&P [REDACTED]

Printed by Ramco

Date : 12/20/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : 11-001580-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1999.40

A/C TSN : 7862.10

Landings : 8885

AIRFRAME ENTRIES

08A510-02 Phase 2

C/W Phase 2 Inspection IAW Beech 90 MM

08A3240-01 Cleveland Nose Wheel ICA Ref. CMM 040-20400

C/W Cleveland Nose Wheel ICA Ref. CMM 040-20400

08A3240-02 Left Hand Cleveland MLG Brakes & Wheels ICA Ref. Manual 199-90

C/W Left Hand Cleveland MLG Brakes & Wheels ICA Ref. Manual 199-90

08A3240-04 Right Hand Cleveland MLG Brakes & Wheels ICA Ref. Manual 199-90

C/W Right Hand Cleveland MLG Brakes & Wheels ICA Ref. Manual 199-90

08A3230-06 NLG Actuator Clevis Inspection Ref CMM 32-20-00

C/W NLG Actuator Clevis Inspection Ref CMM 32-20-00 No defects noted

08A3230-04 Left Hand MLG Actuator Clevis Inspection Ref AMM 05-25-05-601 item 7

C/W Left Hand MLG Actuator Clevis Inspection Ref AMM 05-25-05-601 item 7 no defects noted

08A3230-05 Right Hand MLG Actuator Clevis Inspection Ref AMM 05-25-05-601 item 17

C/W Right Hand MLG Actuator Clevis Inspection Ref AMM 05-25-05-601 item 17 No defects noted

08A3230-02 Landing Gear Hydraulic System Filter Ref. AMM 12-20-35-301

Removed Hydraulic System Filter PN AN6235-3A, Installed new PN AN6235-3A. Ops check and leak check good. Done IAW Beech C-90 MM.

08A7120-02 Left Hand Engine Mount Vibration Isolators Replacement

Removed and replaced Left Hand Engine Mount Vibration Isolators P/N LM4275A12 IAW Pratt and Whitney MM *Beech 90 mm*

CMP6110-04 Raisbeck Propeller Inspection ICA Ref. Manual 85-120 ATA 61

C/W LH Raisbeck Propeller Inspection IAW Raisbeck Propeller Inspection ICA Manual 85-120 ATA 61 No defects noted

MXRD-001783-2016 LH Engine fuel nozzles Due Flow Check

Removed LH Engine Fuel nozzle kit P/N PT6A-21-10-3-1 KIT And Installed previously tested nozzle kit P/N PT6A-21-10-3-1 KIT IAW Pratt And Whitney MM Leak check good *WO # 7533*

Installed Part #: PT6A-21-10-3-1 KIT ; Installed SN #: egm16-Dec124-1 ; Removed Part #: PT6A-21-10-3-1 KIT ; Removed Serial#: EGM16- DEC15;
Installed Part #: PT6A-21-10-3-1 KIT ; Installed SN #: egm16-dec1-2 ; Removed Part #: PT6A-21-10-3-1 KIT ; Removed Serial#: 51CRT;

08A7120-04 Right Hand Engine Mount Vibration Isolators Replacement

Removed and replaced RT Hand Engine Mount Vibration Isolators P/N LM4275A12 IAW Pratt and Whitney MM *Beech 90 mm*

CMP6110-04 Raisbeck Propeller Inspection ICA Ref. Manual 85-120 ATA 61

C/W RH Raisbeck Propeller Inspection IAW Raisbeck Propeller Inspection ICA Manual 85-120 ATA 61 no defects noted

MXRD-001784-2016 RH Engine fuel nozzles Due Flow Check

Removed RH Engine Fuel nozzle kit P/N PT6A-21-10-3-1 KIT And Installed previously tested nozzle kit P/N PT6A-21-10-3-1 KIT IAW Pratt And Whitney MM Leak check good *WO # 7533*

08A5300-01 Raisbeck Strake inspection ICA Ref Manual 85-120 Section 53-00-00-05

C/W Raisbeck Strake inspection IAW Raisbeck Strake inspection ICA Manual 85-120 Section 53-00-00-05

08A2120-01 Evaporator Air Filter Replacement - Ref. AMM 12-10-11-301

Complied with Evaporator Air Filter Replacement. Removed old Evaporator Air Filter P/N 90-555101-0001. Installed new Evaporator Air Filter P/N 90-555101-0001. Work done in reference to Beech King Air 90 series MM.

Installed Part #: 90-555101-0001 ; Removed Part #: 90-555101-0001 ;

08A2500-01 Emergency Equipment

C/W Emergency Equipment Insp IAW Beech 90 MM not defects noted

08A2770-01 SB 27-3459 Gust Lock Inspection

C/W SB 27-3459 Gust Lock Inspection no defects noted

08A2520-02 Spectrum Medical Annual Inspection Ref. Manual #6011MM Pg. 78

C/W Spectrum Medical Annual Inspection IAW Spectrum Medical Annual Inspection Manual #6011MM no defects noted

MXRD-001787-2016 Left Wing 2 static wicks are bad.

Removed and replaced the 2 bad static wicks and replaced with new, part number DD1W. Ops check good. All work done in reference with Beechcraft King Air 90 AMM.

MXRD-001788-2016 Right wing fuel lanyard broken.

Installed Right outboard wing fuel lanyard IAW Beech 90 MM *P/A m50738-3*

08A1220-01 200 Hour Lubrication Ref. AMM 12-20-11

Date : 12/20/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001580-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1999.40
A/C TSN : 7862.10
Landings : 8885

- 29
PAGE

AIRFRAME ENTRIES

C/W 200 Hour Lubrication Ref. AMM 12-20-11

08A1220-02 400 Hour Lubrication Ref. AMM 12-20-11

C/W 400 Hour Lubrication Ref. AMM 12-20-11

08A7100-03 Compressor Desalination Wash

C/W Compressor Desalination Wash I/W Pratt and Whitney MM And Beech 90 MM

99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 12/20/2016

Signature: [REDACTED]

Dominic Mercer

A&P [REDACTED]

Tech Log #: tl-001580-2016

Printed by Ramco

Date : 12/22/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : tl-001619-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1999.40

A/C TSN : 7862.10

Landings : 8885

AIRFRAME ENTRIES

MXRD-001813-2016 LH Prop control loose

Removed Detent Spring PN 50-524478-15, Installed new PN 50-524478-15. Ops check good. Done IAW Beech C-90 MM.

MXRD-001815-2016 Rudder Boost Inop

Removed Switch PN 101-384119-5, Installed new PN 101-384119-5. Ops check good. Done IAW Beech C-90 MM.

Date : 12/22/2016

Signature: [REDACTED]

Frank Barr

A&P [REDACTED]

Tech Log #: tl-001619-2016

Printed by Ramco

Date : 12/22/2016

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : tl-001619-2016

EagleMed LLC

6601 W Pueblo Dr,
Wichita, KS 67209

Phone : (316) 613-4855

Hobbs : 1999.40

A/C TSN : 7862.10

Landings : 8885

AIRFRAME ENTRIES

99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 12/22/2016

Signature: [REDACTED]

Frank Barr

A&P [REDACTED]

Tech Log #: tl-001619-2016

Printed by Ramco

BOOK

Date : 12/22/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001619-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1999.40
A/C TSN : 7862.10
Landings : 8885

AIRFRAME ENTRIES

MXRD-001619-2016 Maintenance request test flight
Post Maintenance Test Flight Satisfactory. No Defects noted. Aircraft Approved for service.

Date : 12/22/2016

Signature: [Redacted]

Lic. Type Cert

Tech Log #: tl-001619-2016

Printed by Ramco

Date : 12/22/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-001619-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1999.40
A/C TSN : 7862.10
Landings : 8885

AIRFRAME ENTRIES

MXRD-001816-2016 Rudder boost failed ground test
Removed L/H and R/H Rudder Boost Solenoid valves, P/N 717 SOLENOID. Installed new L/H and R/H Rudder Boost Solenoid valves, P/N 717 SOLENOID. Ops checked good on ground. Work done in reference to Beech King Air 90 series MM.

Date : 12/22/2016

Signature: [Redacted]

Stephen Weir

A&P [Redacted]

Tech Log #: tl-001619-2016

Printed by Ramco

Date : 12/29/2016
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-001637-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 2003.80
A/C TSN : 7866.50
Landings : 8889

AIRFRAME ENTRIES

MXRD-001847-2016 VSI shows the aircraft is in a climb while in level flight.
R/R Pilot VSI p/n 100-384054-1 s/n off: 6163 on: 356555. Op check and leak check good. All work performed IAW King Air 90 AMM.
Installed Part #: 100-384054-1 ; Installed SN #: 356555 ; Removed Part #: 100-384054-1 ; Removed Serial#: 6163;

Date : 12/29/2016

Signature: [Redacted]

Dan Palmer

A&P [Redacted]

Tech Log #: TL-001637-2016

Printed by Ramco

Date : 01/05/2017
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000020-2017

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 2015.40
A/C TSN : 7878.10
Landings : 8900

31
PAGE

AIRFRAME ENTRIES

08A3400-03 GPS Update #1

I certify that the Garmin GPS database was updated accordingly for the Garmin GPS 400W/500W, current cycle 1701, expires 2017-Feb-2.

99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 01/05/2017

Signature: [Redacted]

Tech Log #: TL-000020-2017

Peter Giegerich

A&P [Redacted]
EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Printed by Ramco

Hobbs : 2032.00
A/C TSN : 7894.70
Landings : 8918

Date : 01/11/2017
A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : TL-000048-2017

AIRFRAME ENTRIES

MXRD-000053-2017 Found broken static discharger on right outboard wing.
Removed damaged static discharger from base and replaced with new p/n 101-380053-11 IAW Beech C90 MM Ch. 23-60-01. Bonding check satisfactory. Aircraft is approved for return to service.

99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 01/11/2017

Signature: [Redacted]

Tech Log #: TL-000048-2017

Peter Giegerich

A&P [Redacted]

Printed by Ramco

Date : 01/19/2017

A/C Reg # : N1551C

Model # : C90A

Serial # : LJ-1365

Manufacturer # : BEECHCRAFT

Tech Log # : TL-000065-2017

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 2045.40
A/C TSN : 7908.10
Landings : 8930

AIRFRAME ENTRIES

MXRD-000065-2017 Flap position indicator shows approach flaps when selector is up and flaps visually verified in the up position.
R/R flap position transmitter p/n 559-1 s/n off: 6246A on: 10910A. System checks good. All work done IAW King Air 90 AMM..
Installed Part #: 559-1 ; Installed SN #: 10910A ; Removed Part #: 559-1 ; Removed Serial#: 6246A;

Date : 01/19/2017

Signature: [Redacted]

Tech Log #: TL-000065-2017

Dan Palmer

A&P [Redacted]

Printed by Ramco

Date : 01/20/2017
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : TL-000065-2017

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 2045.40
A/C TSN : 7908.10
Landings : 8930

AIRFRAME ENTRIES

MXRD-000093-2017 standby battery has blown fuses.
R/R burnt fuses p/n GMW-5. System checks good. All work done IAW King Air 90 AMM.

Date : 01/20/2017

Signature: [REDACTED]

Dan Palmer

A&P [REDACTED]

Tech Log #: TL-000065-2017

Printed by Ramco

Date : 01/19/2017
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000065-2017

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 2045.40
A/C TSN : 7908.10
Landings : 8930

AIRFRAME ENTRIES

MXRD-000088-2017 Cabin door steps loose.
Replaced lower step bracket with new part #50-430043-889U and replaced door retract cable assy with new part #50-430043-437 IAW Beech King Air 90 Series MM Ch 52.

Date : 01/19/2017

Signature: [REDACTED]

James Curtis

A&P [REDACTED]

Tech Log #: tl-000065-2017

Printed by Ramco

Date : 02/15/2017
A/C Reg # : N1551C
Model # : C90A
Serial # : LJ-1365
Manufacturer # : BEECHCRAFT
Tech Log # : tl-000107-2017

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 2074.80
A/C TSN : 7937.50
Landings : 8964

AIRFRAME ENTRIES

08A3400-03 GPS Update #1
Performed GPS update in accordance with Garmin instruction, Next due Mar 2, 2017
Aircraft approved for return to service

Date : 02/15/2017

Signature: [REDACTED]

Johnny Cavitt

A&P [REDACTED]

Tech Log #: tl-000107-2017

Printed by Ramco