

PROPELLER S/N

FY 3166

PROPELLER MODEL HC-D4N-3C/D9290K

PROPELLER LOGBOOK

R/H

HARTZELL

HARTZELL PROPELLER INC.

One Propeller Place
Piqua, Ohio 45356-2634 U.S.A.
Telephone: 937.778.4200
Telex: 4332032
Fax: 937.778.4391

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
Date : 09/04/2015 A/C Reg # : N1551C Prop Model # : HC-d4n-3c Prop Serial # : fy3166 Position Code : prop 1 Tech Log # : tl-001676-2015 EagleMed LLC 6601 W Pueblo Dr, Wichita, KS 67209 Phone : (316) 613-4855 Hobbs : 1403.70 A/C TSN : 7266.40 Landings : 8199 Prop TT : 2243.10 Prop TSO : 1288.20			
PROPELLER ENTRIES			
MXRD-001507-2015 R&R both prop de-ice harnesses. Removed R/H and L/H prop boot de-ice harnesses P/N 3E2092-4 and installed new R/H and L/H prop boot de-ice harnesses P/N 3E2092-4. Ops check good. Work done in reference to Beech King Air 90 series MM. 99A9999-99 I certify that this aircraft/engine/prop has been inspected IAW MFG current inspection program and was determined to be in airworthy condition			
Date : 09/04/2015		Signature: 	Tech Log #: tl-001676-2015
Ross Hausmann		A&P 	Printed by Ramco

Date : 12/31/2015 A/C Reg # : N1551C Prop Model # : HC-d4n-3c Prop Serial # : fy3166 Position Code : prop 1 Tech Log # : tl-002444-2015 EagleMed LLC 6601 W Pueblo Dr, Wichita, KS 67209 Phone : (316) 613-4855 Hobbs : 1593.80 A/C TSN : 7456.50 Landings : 8402 Prop TT : 2433.20 Prop TSO : 1478.30			
PROPELLER ENTRIES			
08A510-04 Phase 4 Complied with phase 4 of the Beechcraft 90-series inspection program. CMP6110-04 Raisbeck Propeller Inspection ICA Complied with propeller inspection IAW Raisbeck instructions for continued airworthiness in conjunction with phase 4 of the Beechcraft 90-series inspection program. Ops checks normal. No defects noted. 08A1220-01 200 Hour Lubrication Complied with 200 hour lubes IAW Beechcraft 90-series MM. Ops and leak checks good. 99A9999-99 I certify that this aircraft/engine/prop has been inspected IAW MFG current inspection program and was determined to be in airworthy condition			
Date : 12/31/2015		Signature: 	Tech Log #: tl-002444-2015
Ross Hausmann		A&P 	Printed by Ramco

Date : 06/17/2016
A/C Reg # : N1551C
Prop Model # : HC-d4n-3c
Prop Serial # : fy3166
Position Code : prop 1
Tech Log # : tl-000795-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1806.90
A/C TSN : 7669.60
Landings : 8686
Prop TT : 2646.30
Prop TSO : 1691.40

PROPELLER ENTRIES

08A510-01 Phase 1
C/W Phase 1 inspection. Work done in reference to Beech King Air 90 series MM.
CMP6110-04 Raisbeck Propeller Inspection ICA Ref. Manual 85-120 ATA 61
C/W Raisbeck Propeller Inspection IAW Raisbeck Propeller Inspection ICA Ref. Manual 85-120 ATA 61 no defects noted
08A1220-01 200 Hour Lubrication
C/W 200 Hour Lubes. Work done in reference to Beech King Air 90 series MM.
99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 06/17/2016

Signature

Curtis Murphy

A&P

Tech Log # : tl-000795-2016

Printed by Ramco

Date : 12/21/2016
A/C Reg # : N1551C
Prop Model # : HC-d4n-3c
Prop Serial # : fy3166
Position Code : PROP 1
Tech Log # : TL-001580-2016

EagleMed LLC
6601 W Pueblo Dr,
Wichita, KS 67209
Phone : (316) 613-4855

Hobbs : 1999.40
A/C TSN : 7862.10
Landings : 8885
Prop TT : 2838.80
Prop TSO : 1883.90

PROPELLER ENTRIES

08A510-02 Phase 2
CW Phase 2 Inspection IAW Beech 90 MM
CMP6110-04 Raisbeck Propeller Inspection ICA Ref. Manual 85-120 ATA 61
C/W LH Raisbeck Propeller Inspection IAW Raisbeck Propeller Inspection ICA Manual 85-120 ATA 61 No defects noted
08A1220-01 200 Hour Lubrication Ref. AMM 12-20-11
C/W 200 Hour Lubrication Ref. AMM 12-20-11
99A9999-99 The Inspection(s) and or Maintenance Identified above, was determined to be in airworthy condition and approved for return to service

Date : 12/21/2016

Signature

Dominic Mercer

A&P

Tech Log # : TL-001580-2016

Printed by Ramco
