

NATIONAL TRANSPORTATION SAFETY BOARD

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►

ACCIDENT NUMBER:

CEN17LA121

For Use In All Modal Investigations

REGISTERED OWNER (name and address) EagleMed, LLC 6601 W Pueblo Drive Wichita, KS 67209		IDENTIFICATION NUMBER N1551C	
		MAKE Beech	
LOCATION Rattan, Oklahoma	DATE OF ACCIDENT 2/14/17	MODEL C90A	
RETAINED BY NTSB REPRESENTATIVE Timothy Sorensen		TITLE Aviation Accident Investigator	DATE 4/7/17
The National Transportation Safety Board has ☒ has not ☐ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released. ☐ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE Timothy Sorensen		TITLE Aviation Accident Investigator	DATE 4/7/17
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.) I HEREBY ACKNOWLEDGE: ☐ Receipt of the above described wreckage. ☒ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT [REDACTED]		TITLE Claim Manager	DATE 4/10/2017
PHONE NUMBER & EMAIL [REDACTED]		[REDACTED]	
REMARKS: Retained by NTSB: Starter-Generator -- Left (Goodrich, model 23048-016, s/n P1432); Starter-Generator -- Right (Safran, model 23048-016, s/n 1092M); Generator Control Unit -- Left (Lucas Aerospace, p/n 31435/51538-001A, s/n 96514); Generator Control Unit -- Right (Lucas Aerospace, p/n 31435/51538-001A, s/n 93348).			