

Recommendation:

Centennial airport's south side is accident prone and is nicknamed 'Centennial Triangle', after the infamous Bermuda Triangle.

Putting a Doppler Radar or Wind Shear Detection System in place is highly recommended due to number of accidents that are all weather related.

Some aircrafts are lacking shoulder harness. had we had a shoulder harness in our airplane my student most likely would have walk away uninjured.