



RECORD OF CONVERSATION

Aaron M. Sauer
Aviation Accident Investigator
Central Region

Date: March 14, 2017
Person Contacted: Pilot – Stephen Wilemon
NTSB Accident Number: CEN17LA126

Narrative:

During a conversation with the pilot, he stated that while he was taxiing the airplane for departure to runway 36, the airplane suddenly veered to the right. The pilot attempted to correct the right turn by applying the left brake, however, the attempt was unsuccessful and the airplane entered a drainage ditch. The airplane came to rest upright off the taxiway surface in the drainage ditch.