



Photo 1 – Propeller



Photo 2 – Propeller Blade 2 Hub Cavity with Fractured Actuating Pin