



The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
FAA Inspector Findings
CEN17FA248
Catawba Wisconsin
July 1 2017

The FAA inspector who examined the airplane at the accident site reported:

A examination of the airplane did not show obvious mechanical anomalies. There was a severe post-impact fire that completely consumed the front portion of the fuselage and engine. The engine could not be examined in detail due to the severe fire damage.

Alexander Lemishko



Senior Air Safety Investigator
NTSB Central Region Aviation