



Photo 1 – View of the airplane off the side of the runway



Photo 2 – View of damage to the right horizontal stabilizer