

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Bennett State: CO

ZIP: 8102 Country: USA

Latitude: approx 39.84 Longitude: approx -104.5

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 06/08/2017 Local Time: 1330
mm/dd/yyyy

Time Zone: Mtn

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N7328V

Manufacturer: Bellanca

Model: 17-30 (Super Viking)

Serial Number: 30207

Year of Manufacture: 1969

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 3000 lbs

Weight at Time of Accident/Incident: 2600 lbs

Number of Seats: 4 Flight Crew Seats: 2

Cabin Crew Seats: 0 Passenger Seats: 2

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate (Check all that apply)

Standard

☒ Normal

☐ Aerobatic

☐ Balloon

☐ Commuter

☐ Transport

☐ Utility

Special

☐ Restricted

☐ Limited

☐ Provisional

☐ Special Flight

☐ Experimental

☐ Special Light-Sport

☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)

☐ None

☐ Unknown

Landing Gear

(Check all that apply)

☒ Retractable

☒ Tricycle

☐ Amphibian

☐ Emergency Float

☐ Float

☐ Hull

☐ Other Launch/Recovery System

☐ None

☐ Tailwheel

☐ High Skid

☐ Skid

☐ Ski

☐ Ski/Wheel

☐ Unknown

Engine Type (Select one)

☒ Reciprocating

☐ Turbo Shaft

☐ Turbo Prop

☐ Turbo Jet

☐ Turbo Fan

☐ Electric

☐ Liquid Rocket

☐ Solid Rocket

☐ Hybrid Rocket

☐ None

☐ Unknown

Fuel System Type (Reciprocating)

☐ Carburetor

☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Continental	IO520-D	TBD	TBD	300	2670	2.5	590
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☐ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☒ Unknown

Date Last Inspection: 05/03/2017
mm/dd/yyyy

Airframe Total Time: 2670 hrs
hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: McCauley

Model: TBD

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: TBD

Model or Part No.: TBD

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)

☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☐ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☐ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: Strike Finder

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Jeffrey Thomas HandrockCity: AuroraState: COZIP: 80013Fractional Ownership Aircraft: ☐ Yes ☐ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)

- ☐ Armed Forces
☐ Federal
☐ State
☐ Local

☐ Unknown**Revenue Operation for FAR 121, 125, 129, 135**

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☒ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Front RangeAirport Identifier: KFTGProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/ADistance From Airport Center: 2.5 smDirection From Airport: North East degrees trueAirport Elevation: 5500 ft. msl**Runway Information**

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION**"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident**

☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: _____

City of Residence: _____

Middle Initial: _____

State: _____ ZIP: _____

Last Name: _____

Country: _____

Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy

Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

mm/dd/yyyy

Medical Certificate Limitations**Medical Certificate Special Issuance****Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:**

mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s)

(Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings**Student Endorsements** (Include dates)**Flight Time** (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available	Used
☐ None	☐ None
☐ Lap only	☐ Lap only
☐ 3-point	☐ 3-point
☐ 4-point	☐ 4-point
☐ 5-point	☐ 5-point
☐ Unknown	☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)

Crew Name and Address		Seat Occupied	Injury
First Name: _____	City of Residence: _____	☐ Left ☐ Center ☐ Right	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Middle Initial: _____	State: _____ ZIP: _____	☐ Front ☐ Rear ☐ Single ☐ Unknown	
Last Name: _____	Country: _____		
Pilot Certificate(s) (Check all that apply)		Restraint Type:	Inflatable Restraints
☐ None ☐ Private ☐ Student	☐ Flight Instructor ☐ Recreational ☐ Sport	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown
☐ Commercial ☐ Airline Transport ☐ Flight Engineer	☐ US Military ☐ Foreign		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs	

Crew Name and Address		Seat Occupied	Injury
First Name: _____	City of Residence: _____	☐ Left ☐ Center ☐ Right	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Middle Initial: _____	State: _____ ZIP: _____	☐ Front ☐ Rear ☐ Single ☐ Unknown	
Last Name: _____	Country: _____		
Pilot Certificate(s) (Check all that apply)		Restraint Type:	Inflatable Restraints
☐ None ☐ Private ☐ Student	☐ Flight Instructor ☐ Recreational ☐ Sport	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown
☐ Commercial ☐ Airline Transport ☐ Flight Engineer	☐ US Military ☐ Foreign		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs	

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)

Name and Address	Seat	Injury	Restraint Type	Inflatable Restraints	Age
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION**Last Departure Point**

Airport ID: _____

City: _____

State: _____

Country: _____

Time of Departure

Time: _____

Time Zone: _____

Destination

Airport ID: _____

City: _____

State: _____

Country: _____

Type Flight Plan Filed

☐ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR

Activated? ☐ Yes ☐ No ☐ Unknown**Type of ATC Clearance/Service** (Check all that apply)

☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

_____ ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE**Source of Pilot Weather Information**

(Check all that apply)

☐ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☐ On-Board Weather

Weather Observation Facility

Facility ID: _____

Observation Time: _____

Time Zone: _____

Distance from Accident Site: _____ nm

Direction from Accident Site: _____ degrees true

Basic Conditions

☐ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☐ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Ceiling

☐ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Temperature: _____ (C) or _____ (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
or _____ MB**Lowest Cloud Condition Height**

_____ ft agl

Ceiling Height

_____ ft agl

Wind Direction☐ Variable

-or-

Direction: _____ degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-

Speed: _____ kts

Wind Gusts☐ Not Gusting

-or-

Speed: _____ kts

Visibility

_____ miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☐ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☐ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount **Type**
☐ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount **Type**
☐ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply) **Severity**
☐ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- | | |
|-----------------------------|-----------------------------------|
| ☐ None | ☐ Substantial |
| ☐ Minor | ☐ Destroyed |
| | ☐ Unknown |

Aircraft Fire

- | | |
|---------------------------------|---|
| ☐ None | ☐ Both Ground and In-Flight |
| ☐ In-Flight | ☐ Fire at Unknown Time |
| ☐ On-Ground | ☐ Unknown |

Aircraft Explosion

- | | |
|---------------------------------|---|
| ☐ None | ☐ Both Ground and In-Flight |
| ☐ In-Flight | ☐ Explosion at Unknown Time |
| ☐ On-Ground | ☐ Unknown |

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/Cycles
On Part

_____ Hours

_____ Cycles

Time Since This Part
Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

_____ Gallons

Fuel Type

☐ 80/87☐ 100 Low Lead☐ 100/130☐ 115/145☐ Jet A☐ Jet A-1☐ Jet B☐ JP8☐ Automotive☐ Other, specify _____

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Substantial☐ Minor☐ None

Registered Owner of Other Aircraft

Pilot of Other Aircraft

Name: _____

Name: _____

City: _____

City: _____

State: _____ ZIP: _____

State: _____ ZIP: _____

Country: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

Name of Pilot/Operator: _____

Signature: _____

mm/dd/yyyy

-- or -- ☐ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.
CEN17LA220

Reviewed by NTSB Regional Office
CEN

Name of Investigator
LINDBERG

Date Report Received
6/14/2017

From: [Jeffrey Williams](#)
To: [Liedler Courtney](#)
Cc: [REDACTED]
Subject: Bellanca Super Viking N7328V
Date: Friday, June 9, 2017 1:18:55 PM

Greetings,

Information from the owner of the aircraft.

Approx. 2pm ish Denver time June 8th, My flight instructor and pilot buddy (Barry Gomez) whom I had done some flying with in the Bellanca was PIC of (N7328V) and crash landed in a field near Front Range Airport. There was another person on board whom I do not know nor had I authorized to be in the aircraft as pilot or passenger. Both are alive but in the hospital with back injuries.

Barry Gomez was the CFI who was with me in Ashland KY in Feb when I purchased the plane. Barry was in the back seat during my last hour of required flight check for insurance purposes (with the previous owner Sam Rice in Ashland KY). Barry had flown the plane with me as PIC two weeks ago for about 1 hour 20 minutes and was familiar with the aircraft as he was there in Ashland KY when the owner was giving us lessons on flying it both in the air and on the ground that included fuel management, emergency landing gear ops, normal speeds and engine parameters and panel layout. Barry also received (by me two weeks ago when he was PIC of N7328V) the same instructions as a refresher course that Sam Rice previous owner, gave us back in Feb on fuel management and Emergency landing gear ops and normal speeds for gear ops and maneuvering (Va). For all intensive purposes since Barry is a CFI and flies daily and I can only get in the air occasionally, I felt Barry Gomez was probably more qualified to fly it than myself. However, I need to stress the fact, that I informed Barry back in Feb that on my solo 1350 mile trip home to Denver from ashland KY, I did mismanage fuel selector valve on 10 mile approach to Hayes Kansas and for an instant I experienced rough engine as a tank was running dry. My training from Sam Rice and my knowledge of the POH kept me calm and I diagnosed the situation within about 5 seconds and switched my fuel selector valve to the correct tank without any engine outage. While I was embarrassed to tell Barry I did that, my goal was to tell him that the Viking is NOT A CESSNA and as PIC of that aircraft fuel management is a full time job on that plane. Furthermore, at one time Barry had expressed interest in becoming a partner on the aircraft as he needed to log plenty of hours to become a full time ATP. So my goals of getting current on IFR rating, flying the plane with an experienced CFI and letting him log a few hours in the plane as payment for his CFI skills and training were reasons he was allowed to fly the plane solo.

Barry knew where all the manuals for the plane were. He had over two hours of flight time in the plane and about an hour of ground instruction pre flight on it.

Barry was in my hangar in May when it was on jack stands and we swung the gear with power and we also pulled the emergency gear lever which lets gravity drop the gear. We did that about 3 times....The plane was on jacks and cowls were off the plane as it had just come from the Front Range A&P Shop where they did the engine inspection on the cylinders for compressions and to verify what push rod tubes were leaking. The bottom cowl requires the plane be on jacks to swing the front gear up to remove and or put it on. It is a pain in the butt and takes about 30 minutes to do that procedure and rather than pay a shop to do that, I gave them the plane with cowls off and when the job was finished at the shop, I taxied the plane to my hangar with cowls off. Its about 600 yds. from the shop to my hangar. That is not enough time for the engine to even show oil temp readings. My point is: this engine had been inspected and confirmed to be airworthy in Feb 2017 during pre purchase and from Front Range Mechanics in May. I find it hard to believe that there was any failure of that engine.

I was at the crash site and it appears the left main tank is nearly dry with less than 2 gallons of fuel. The other tanks had a reasonable amount of fuel in them. It is my opinion that he failed to properly manage the aircraft fuel supply which caused the engine to stop and force the landing in the field. Furthermore, he did not follow my instructions to top the tanks off as the plane had flown about 2.5 hours since last being

filled. BUT I am checking with the mgrs at Front Range who would verify that statement by looking for fuel receipts that would be associated with the aircraft. Anyhow, to my knowledge. there would have been maybe 15 minutes of fuel in the left MAIN TANK after I flew it the day before. The Right main tank would have have about 30-40 minutes left. The Aux tanks probably about 45 minutes in each tank. If you do the math that means after about 2.5 hours of flying since the tanks were filled, the aircraft had a little over 2 hours of fuel onboard. Those numbers validate my estimate of the time the aircraft was flown since fill up.

On Wed (June 7th) my wife and I flew the plane for approx. 1 hour 5 minutes in the Front Range pattern and out in the practice zone over Bennett. The aircraft flew absolutely flawlessly with no engine anomalies. All engine parameters were within specs and nothing could be noted as being "suspect". At 7000 ft the engine was nearly squared at about 2300 rpm and 22 manifold indicating nearly 175MPH.

After being airborne about 30 minutes I let my wife take the controls for about 10 minutes and during her time controlling the aircraft I monitored all engine parameters including fuel levels and found all normal.

Wednesday nights flight and two weeks ago with Barry, I found NOTHING that could be noted or squawked on performance. Furthermore, I asked Barry during our flight two weeks ago while he was PIC if the plane was comparable to the 182 he has been flying that are complex high performance with 300hp engines and he said the plane was super stable and flew very fast and was a little "hot rod". When Barry landed the plane at Front Range he noted the left brake was a little softer than the right. I told him I would have The A&P's bleed the left brake to make them even, as the right was bled in Feb when they replaced the right strut, so it was totally possible that they would not be have even pressure . A few days later I gave the keys to Barry so he could taxi the plan over to the mechanics as I was going to be out of town and could not do it myself. The A&P's never did the brake job as they said they did not know how. (REALLY)?????. So I taxied the plane back to my Hangar the following week on Tuesday June 6th after work. Furthermore, when the plane was in their shop I told them to grab the plane logs out of the briefcase in the back and properly add and sign off on the work they did the prior month on the Engine mounts. They never did that because they told me they did not know where they were. I told them when I brought the plane in on both occasions ALL THE LOGS ARE IN THE BIG BLACK BRIEFCASE IN BAGGAGE COMPARTMENT...Thus that is why that brief case was still in the plane when they crashed. So we need to figure out why Eldon the A&P at Front Range Flight School did the work on my plane collected 1350 bucks from me and never signed my logs. Also, I find it very hard to believe that they would have my plane in their shop for about 5 days and not know how to bleed the brakes on a Viking. I can find ALL that information online in 30 seconds. PLUS the guys in Alexandria MN at the factory always answer the phones and answer any questions!

Lindberg Joshua

From: Jeffrey Williams [REDACTED]
Sent: Wednesday, June 14, 2017 1:04 PM
To: Lindberg Joshua; [REDACTED]
Cc: Hope DeLong
Subject: Re: NTSB Form 6120.1

The previous owner gave me the Prop# 697805

He is looking to see if he can find the SN for the engine and manufacturer date from old records. I would have no "old" records for the engine.

On Wednesday, June 14, 2017 11:01 AM, Jeffrey Williams [REDACTED] > wrote:

Greetings all,

I filled out the form as much as I can at this time. I believe Sidney or another official has the Engine logbook as well as the aircraft logbook. Thus I do not know the Engine S/N at this time, nor the model of the Propeller. After looking at all my files pertaining to the aircraft I can not find those items listed anywhere. As far as aircraft total time, I am approximating the TT on engine and airframe at time of accident. They could be off an hour or two since I do not know the exact Tach time when it crashed. I have the exact tack time the aircraft had the Right Main Strut fixed in Ashland KY before I flew it home to Denver in March. It was: 1499.19. All the numbers I filled out on the 6120.1 form are based off that TACH time and I extrapolated the final TACH based on known flights and durations since leaving Ashland KY. Forgive me for not having more exact numbers regarding the aircraft as I have only had it in my hangar since March.

Since I have no idea about the crew onboard the aircraft when it went down I can not fill out any of that information. I know Barry Gomez has multiple CFI ratings/Certificates but I do not know how many hours he has logged in his career. I know that he was being interviewed by Key Lime Air for a job and last week he called me to tell me he needed a few more hours logged before he could get a job with them. He asked me if he could fly the plane to help him get some of those hours in trade for him instructing me with my IFR currency issues and I told him that sounded OK since he had flown the plane as PIC and as Passenger on a few occasions in the recent past. Furthermore, he had taxied the plane back and forth from my hangar to the Front Range Flight School A&P shop on at least 2 occasions and he told me he logged that time as PIC.

As far as the other person onboard I have zero information. I know nothing about who he is or why he was in the aircraft with Barry Gomez. Actually I don't even know who was sitting in the left seat when they crashed. Maybe it was not Barry Gomez. As far as I am concerned the two people onboard the aircraft took a "joy" ride in it without my permission.

When Barry Gomez sat left seat with me on May 28th he had squawked the left brake pedal as not being equal to the right brake pedal. Since Barry worked for Front Range as a CFI and as a maintenance shop scheduler, I told him to take the plane into the shop to have them bleed the left brake pedal and I gave him the keys to my hangar and plane so he could perform that maintenance task for me while I was out of town. That is basically the entire reason Barry had permission to be in that plane. The day they crashed it, Barry and I had scheduled an evening flight for training and he was "supposed" to go get the plane and top off the the tanks and have the plane ready for us to leave Front Range on an expedited departure to save time and Daylight hours. Since the Mechanics at Front Range Flight School never did bleed the left brake, I told Barry that when I flew it the night before after deploying the gear for landing if you pump the brakes once they appeared to be even to me when I did my 2 touch and goes and if he wanted to take the plane up for a couple patterns to check that he could. I did not give him permission to go "joy" ride in the aircraft for pleasure purposes. It was based off of his squawk on our last flight together and I wanted him to know the aircraft was fit to fly. Finally, Barry was instructed to TOP OFF THE TANKS and he failed to do fulfil that request which in a Bellanca super Viking that is very risky because there are 4 tanks all separate from each other with roughly 1 hour and 5 minutes of safe flying on each tank. . If you do not know how much fuel is in each tank before you fly you are asking for trouble. All instructions he received by the previous owner when we were in Ashland KY and by me on the ground or in the air was that before each flight you must visually check the tanks and know how much time was flown on each tank during the last flight to be able to safely calculate the time left on each one. I told him how much time had been flown on the aircraft since I last filled it up

in a txt msg which I have as proof and I also told him that before anyone flew it they all needed to be topped off. I have all of this dialogue on txt msg with Barry on the day they crashed. I can prove he disregarded my instructions and flew that plane without topping the tanks off because Front Range Airport sent me all the fuel receipts for my tail number yesterday. The last time that plane was at the fuel pit was MAY 28th...

Regards,

Jeffrey