

AIRFRAME**Company****Manufacturer**

AIR TRACTOR, INC.

Model

AT-602

Serial #

602-1183

Tach Time

4155.4

A/C Cert. Date**Total Time**

4155.4

Tail Number N4196Y

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
*02-19-10 11/15/02	SUPERSEDED BY AD 2004-15-15/				X	N/A	
*04-15-15 09/07/04	AFT FUSELAGE UPPER LONGERON AND DIAGONAL TUBE/	1/5/16	DNA S/N		X	N/A	Brandon Goergen A&P [REDACTED]
*05-13-12 08/05/05	HORIZONTAL STABILIZER SPAR ATTACH EYEBOLTS/	4/2/17	CW per (e),(1) and SL129 by checking eyebolt torque. Bolts to be replaced at 5000 TT		X	4/2018 Each Annual	Brandon Goergen A&P [REDACTED]
*06-22-08 12/01/06	SUPERSEDED BY AD 2007-13-17/	4/2/17			X	N/A	
*06-23-09 12/14/06	WING MAIN SPAR LOWER CAP/	1/5/16	CW per SL240 at factory. Next due 6500TT		X	6500 TT	Brandon Goergen A&P [REDACTED]
*06-23-14 12/21/06	RUDDER AND VERTICAL FIN HINGE ATTACHING STRUCTURE/	1/5/16	DNA S/N		X	N/A	Brandon Goergen A&P [REDACTED]
*07-10-01 06/12/07	HORIZONTAL STABILIZER BRACE TUBE ASSEMBLY/	1/5/16	DNA S/N		X	N/A	Brandon Goergen A&P [REDACTED]
*07-13-17 08/10/07	SUPERSEDED BY AD 2008-10-12/	4/2/17			X	N/A	
*08-10-12 06/12/08	SUPERSEDED BY AD 2009-11-05/	4/2/17			X	N/A	
08-11-17 07/07/08	SUPERSEDED BY AD 2008-28-01/	4/2/17		X		N/A	
08-26-01 01/28/09	OVERTURN SKID PLATE FRONT AND REAR ATTACHMENTS/	1/5/16	DNA S/N	X		N/A	Brandon Goergen A&P [REDACTED]
*09-11-05 06/01/09	ENGINE MOUNT RING CLUSTERS AND GUSSETS/	1/5/16	DNA S/N		X	N/A	Brandon Goergen A&P [REDACTED]

Airworthiness Directive Compliance Record

Page 1 of 2

PT6A SERIES (CANADA) PT6A-60AG

ENGINE -

Company
Manufacturer
Model
Location
Serial #

PRATT & WHITNEY
PT6A SERIES (CANADA) PT6A-60AG
TSMOH 4155.4
PCE-RG0158 Total Time 4155.4

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
68-06-03 02/28/68	REVERSE CONTROL CABLE TERMINALS/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA [REDACTED]
69-23-06 11/15/69	FUEL PUMP INPUT COUPLING/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA [REDACTED]
*75-06-01 04/01/77	[R4] OIL FILTER/	4/2/17	N/A Model Number		X	N/A	Brandon Goergen A&P IA [REDACTED]
*75-11-04 05/20/75	UNMODIFIED POWER TURBINE SHAFT HOUSING ASSEMBLY/	4/2/17	N/A Model Number		X	N/A	Brandon Goergen A&P IA [REDACTED]
78-12-04 06/19/78	PRESSURE OIL TRANSFER TUBE ASSEMBLIES/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA [REDACTED]
78-17-07 08/31/78	BYPASS VALVE DIAPHRAGM/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA [REDACTED]
80-04-02 02/08/80	PUSH-PULL CONTROL TERMINAL/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA [REDACTED]
80-08-12 04/18/80	FUEL PUMP DRIVE COUPLING SPLINES/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA [REDACTED]
86-10-05 06/05/86	FIRST STAGE COMPRESSOR HUB/	4/2/17	N/A model number	X		N/A	Brandon Goergen A&P IA [REDACTED]
*88-24-02 11/16/88	SUPERSEDED BY AD 93-23-06/	4/2/17			X	N/A	
90-12-05 05/30/90	ENGINE OVERHAUL/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA [REDACTED]
92-15-11 08/17/92	COMPRESSOR DELIVERY AIR LINE ASSEMBLY/	4/2/17	N/A model number	X		N/A	Brandon Goergen A&P IA [REDACTED]
*93-23-06 01/26/94	AIRFRAME CHIP DETECTOR FLAG SYSTEM/	4/2/17	N/A model number		X	N/A	Brandon Goergen A&P IA [REDACTED]
*94-10-02 06/15/94	SUPERSEDED BY AD 95-13-08/	4/2/17			X	N/A	
*95-13-08 07/12/95	AFM AMENDMENT-PLACARD-DISC INSPECTION/	4/2/17	N/A Model Number		X	N/A	Brandon Goergen A&P IA [REDACTED]

* indicates possible recurring inspections © 1995 - 2007 - Tdata, Inc. (Tdata.com)

Prepared by [REDACTED]

Date

4/2/17

Airworthiness Directive Compliance Record
Page 2 of 2

PT6A SERIES (CANADA) PT6A-60AG

97-04-12 03/14/97	COMPRESSOR BLEED OFF VALVE/	4/2/17	N/A Complied with at manufacture	X		N/A	Brandon Goergen A&P IA
*01-20-01 11/05/01	COMPRESSOR BLEED VALVE ASSEMBLIES/	4/2/17	N/A Model Number		X	N/A	Brandon Goergen A&P IA
*02-23-13 12/31/02	TURBINE EXHAUST DUCT WELDS/	4/2/17	N/A no weld repair to ducts		X	N/A	Brandon Goergen A&P IA
04-25-18 01/18/05	WOODWARD PROPELLER GOVERNOR P/N 8210-212H/	4/2/17	N/A Serial Number	X		N/A	Brandon Goergen A&P IA
11-20-51 11/01/11	FIRST STAGE REDUCTION SUN GEAR/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA
*11-25-12 12/28/11	FIRST STAGE REDUCTION SUN GEAR/	4/2/17	N/A Model Number		X	N/A	Brandon Goergen A&P IA
12-09-10 05/23/12	FIRST STAGE REDUCTION SUN AND PLANET GEAR SETS/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA
14-11-05 08/05/14	LIBERATION OF POWER TURBINE BLADES/	4/2/17	N/A Model Number	X		N/A	Brandon Goergen A&P IA
*14-17-08 10/08/14	REVISED BY AD 2014-17-08 R1/	4/2/17			X	N/A	
*14-17-08 R1 06/05/15	COMPRESSOR TURBINE BLADE FAILURE/	4/2/17	N/A Model Number		X	N/A	Brandon Goergen A&P IA
16-05-13 04/22/16	WOODWARD FUEL CONTROL UNITS 2- PLY CU-BE BELLOWS INTEGRITY/	4/2/17	8061-333 FCU Installed. No action required until 4/22/2019 (36 months from affective date of AD)	X		April 22, 2019	Brandon Goergen A&P IA

PROPELLER -Company
ManufacturerHARTZELL
HC-B5MP-3CModel
Location

Tail #

N4196Y

Serial #

EVA 3064

Blade
TSMOH

0 SMOH

Total Time

4155.4

Tail Number N4196Y

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
83-08-01 R1 04/28/83	REVISED BY AD 83-08-01 R2/	4/2/17		X		N/A	
83-08-01 R2 05/11/05	PROPELLER INSTALLATION/	4/2/2017	C/W by proper installation	X		DUE at next removal and installation	Brandon Goergen A&P I
*86-06-02 03/28/86	SUPERSEDED BY AD 2004-21-01/	4/2/2017			X	N/A	
87-05-01 03/12/87	BLADE PILOT TUBE BORE AREA/	1/5/16	DNA	X		N/A	Brandon Goergen A&P I
*87-16-02 07/31/87	SUPERSEDED BY AD 2004-07-25/	4/2/2017			X	N/A	
96-15-04 07/29/96	PROPELLER BLADE SHANK CRACKS/	1/5/16	DNA blade s/n	X		N/A	Brandon Goergen A&P I
96-19-14 10/16/96	HUB, BLADE, OR BLADE CLAMP/	1/5/16	DNA hub S/N	X		N/A	Brandon Goergen A&P I
04-07-25 05/21/04	M10876K PROPELLER BLADES/	1/5/16	DNA BLADE M/N	X		N/A	Brandon Goergen A&P I
*04-21-01 10/19/04	SUPERSEDED BY AD 2006-22-12/	4/2/2017			X	N/A	
*05-14-12 07/29/05	MOUNTING FLANGE BOLTS P/N B-3339/	4/2/2017	DNA affected bolts not installed		X	N/A	Brandon Goergen A&P I
*06-22-12 11/13/06	ENGINE AND PROPELLER MOUNTING FLANGES/	1/5/16	DNA never installed on affected airplanes		X	N/A	Brandon Goergen A&P I
06-24-07 01/03/07	INSPECTIONS AND REPAIRS BY CSE AVIATION/	1/5/16	DNA no work performed by CSE AVIATION	X		N/A	Brandon Goergen A&P I
09-10-14 06/04/09	PROPELLER BLADE COUNTERWEIGHT SLUG BOLTS/	1/5/16	DNA CW at manufacture	X		N/A	Brandon Goergen A&P I