Date	Total Time		Time Since Last Overhaul		**Engine Service and Maintenance Record** Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hrs.	Min.	Hrs.	Min.	
Brought Forward →					
6/23/16	3316.7		tach time		change oil & filter Aeroshell W15W-50 oil [redacted]
2/7/2017	3434.00		TACH TIME ~~5503.5~~ TSFR 1047.7 Completed annual insp per FAR 43 Appd C w AD's attached to logs checked maintenance DRained oil, cut filter RAN ENG Accomplished Compression checks 5 of 6 cyls failed Compression checks. checked fuel filters I certify this Engine has been insp 1/A/W AN Annual insp and found N.T to be in AN airworthy Condition [redacted]		

Date	Aircraft Make	Aircraft Model
1 April 2017	Beechcraft	V35
Aircraft Serial Number	**Aircraft Registration**	**Tach Time**
D8587	N6257V	3431.0

Removed all cylinders and sent off for repair to Gibson Aviation. Received overhauled cylinders (8130 paperwork filed with aircraft logs) and reinstalled IAW current maintenance manual and compression checked #1 78/80 #2 77/80 #3 80/80 #4 78/80 #5 78/80 #6 77/80. Ground run and check, all checks good. Engine is found to be in an airworthy condition at this time. Annual inspection completed at this time in accordance with FAR 43 Appendix D.

TEXAS AVIATORS FLIGHT SERVICE LLC Wichita Falls, Texas

[redacted]