




The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
Vacuum Pump Gasket
Examination
CEN17LA286
Walters Oklahoma
July 8 2017

It was discovered that a gasket (P/N-21051) was installed on the vacuum pump. The gasket is normally used for the installation of a carburetor. The installed gasket did not completely cover the high-pressure oil orifice on the vacuum pump mounting fixture. The proper gasket is (PN-MS9134-01) for the vacuum pump.



Vacuum Pump Gasket Installed



Exemplar Proper Vacuum Pump Gasket

Alexander Lemishko



NTSB Central Region Aviation