

Started up at tiedown idled for 5min while strapping in putting on helmet etc. taxied to load pad and loaded 100gal. took maybe 5-15min. taxied 2 runways halfway down taxiway did runup 1800rpm. checked left then right mag both had 80rpm drop. Cycled prop 3 times. Made call and departed 18 with 1 knotch of flaps. Shortly after take off i pulled prop back to 25 it surged and I pushed it back up a little it surged again and I felt like I was losing power. I pulled the power back to 25 (from 29) and continued to sink so put power to 27 still sinking I put the prop and power to 26-27 squared. I steadily sank so put prop and power to full open and looked for a place to land only available space was a corn and bean field with chainlink fence running through. Tried to make corn field but couldn't get the power 3 pointed in beams went through fence and came to a stop in corn.

AD



V