



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: December 9, 2017
Person Contacted: Lloyd Darter, Owner/Operator
NTSB Accident Number: CEN17LA303 – Marshall, Missouri

Narrative:

Mr. Darter stated that there was no change to the airplane operating limitations or performance data as a result of the STC engine modification.

----- End of entries -----