



N2146R
02-28-2017

Lycoming 0-360-A4M
Tach: 767.6

Aspen Flying Club

13000 E. Control Tower Rd. Englewood, CO 80112


SN: L24719-36A
Hobbs: 6794.3

Removed Pilot right brake master cylinder, resealed with new MS28775-012, MS287110, MS28775-113 and 494-062 seals. Reinstalled and serviced.

Removed all wheel pants for repair. a new weight balance was placed with aircraft records.

All work accomplished referencing piper manuals.

Alberto Pizzato A&P [REDACTED]



N2146R

Piper PA28-181

Aspen Flying Club

13000 E. Control Tower Rd. Englewood, CO 80112

SN: 28-791