



Tim's Aircraft Engines, Inc.

Repair Station No. T22R537Y



Date: 9/2/2016

CUSTOMER INFORMATION



Customer P/O: N5274Q
Engine Make: LYCOMING
Engine Model: IO-360-L2A
Engine Serial: L-28412-51A
A/C Reg. No: N5274Q
Terms: NET30

Customer Invoice

Repair Order: 9809

Item: 1 - Airworthy Engine

Discrepancy

Engine O/H IO-360-L2A / New CMI Steel Cylinders / New Camshaft, Bodies / O/H Servo, Manifold Kit, Starter Motor / New Fuel Pump / New Mags, Harness, Spark Plugs.


Hours

Flat

Subtotal



Corrective Action



Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		1028-B	BALL .6875 DIA (P/O: 8988)		0.00	0.00
1		149NL	Starter Motor Skytec		0.00	0.00
8		15B26588	BODY HYDRAULIC TAPPET (P/O: 9037)		0.00	0.00
2		18A26093	BEARING CRANKSHAFT (P/O: 9037)		0.00	0.00
4		18D26098	BEARING CRANKSHAFT (P/O: 9008)		0.00	0.00
8		18M26105	BEARING CONNECTING ROD (P/O: 9039)		0.00	0.00
1		23D26777	PLUNGER FUEL PUMP LONG (P/O: 8841)		0.00	0.00
7		383-B	NUT .375 24 PLAIN (P/O: 9095)		0.00	0.00
9		383-B	NUT .375 24 PLAIN (P/O: 9028)		0.00	0.00
1		53E22144	VALVE ASSY TEMP CONT. OIL COOL (P/O: 9028)	201949	0.00	0.00
1		61084	SPRING OIL PRESS. RELIEF VALVE (P/O: 8842)		0.00	0.00
1		62B26931	FUEL PUMP-DUAL DIAP.HIGH PR. (P/O: 9095)	RC52155787	0.00	0.00
4		69603	HOSE 1.75 ID X 2.188 OD X 1.75 (P/O: 8977)		0.00	0.00
8		72198	PLUG PISTON PIN (P/O: 8986)		0.00	0.00
8		74637	BUSHING VALVE ROCKER (P/O: 8988)		0.00	0.00
4		75061	BOLT CONNECTING ROD (P/O: 8977)		0.00	0.00
4		75061	BOLT CONNECTING ROD (P/O: 8977)		0.00	0.00

		9028)		
1	75439-1	KIT SEAL GASKET SET	0.00	0.00
1	76121	SHAFT ASSY TACHOMETER (P/O: 9095)	0.00	0.00
1	AA48110-2	OIL FILTER, SPIN-ON	0.00	0.00
1	K4527-38	Ign Upgrade Kit w Champion REM38E Spark Plugs (P/O: 9095)	0.00	0.00
8	LW-12186	NUT CONNECTING ROD BOLT (P/O: 8988)	0.00	0.00
4	LW-13923	BUSHING CONNECTING ROD UPPER 2 (P/O: 9069)	0.00	0.00
4	LW-14078	PIN PISTON (P/O: 9095)	0.00	0.00
8	LW-16266-10-13	CLAMP .13 DIA. FOR 10 SCREW (P/O: 8830)	0.00	0.00
2	LW-16266-10-25	CLAMP .25 ID FOR 10 SCREW CUSH	0.00	0.00
10	LW-16266-10-75	CLAMP (P/O: 8830)	0.00	0.00
1	LW-18840	CAMSHAFT ASSY (P/O: 9028)	0.00	0.00
3	LW-31H0.88	BOLT .3125 18 X .88 LONG HX DR (P/O: 8984)	0.00	0.00
2	MS29512-06	O RING .468 ID X .078 SECT . (P/O: 8174)	0.00	0.00
1	MS35489-20X	GROMMET (P/O: 9095)	0.00	0.00
1	STD-1211	PLUG 2.00 DIA EXPANSION (P/O: 9095)	0.00	0.00
4	STD-1821	HOSE .38 X 2.50 LONG (P/O: 8986)	0.00	0.00
18	STD-2090	NUT .500 20 PLAIN (P/O: 9069)	0.00	0.00
1	STD-2168	NUT .3125 18 NC 3 SLOT. SHEAR (P/O: 9095)	0.00	0.00
1	STD-2231	RING INTERNAL RETAINING .812 (P/O: 9001)	0.00	0.00
1	STD-2246	BOLT .3125 24 X 1.00 LG (P/O: 8988)	0.00	0.00
3	STD-2249	NUT .250 20 SLOTTED (P/O: 9095)	0.00	0.00
2	TIST12.0CA	CYL TITAN 360 540 COMP ASSY STEEL BORE (P/O: 8857)	0.00	0.00
2	TIST12.0CA	CYL TITAN 360 540 COMP ASSY STEEL BORE (P/O: 8904)	0.00	0.00

Item: 2 - Airworthy Engine

Discrepancy	Hours	Subtotal
Disassemble Engine Complete	Flat	0.00

Corrective Action

Disassemble Engine Complete

Labor: \$0.00 **Parts:** \$0.00 **Shipping:** \$0.00 **Item Subtotal:** \$0.00

Item: 3 - Airworthy Engine

Discrepancy	Hours	Subtotal
Clean Engine	Flat	0.00

Corrective Action

Clean Engine

Labor: \$0.00 **Parts:** \$0.00 **Shipping:** \$0.00 **Item Subtotal:** \$0.00