

Avenger Field Airport (KSWW)
Latitude 32-28-02N
Longitude 100-27-59W
Altitude 2,380 ft msl

METAR KSWW 181355Z AUTO 19013G17KT 10SM CLR 26/21 A3013 RMK AO2 T02550214=

METAR KSWW 181415Z AUTO 19011KT 10SM CLR 26/22 A3014 RMK AO2 T02560215=

METAR KSWW 181435Z AUTO 19010KT 10SM CLR 26/22 A3013 RMK AO2 T02560215=

METAR KSWW 181455Z AUTO 19012KT 10SM CLR 26/22 A3014 RMK AO2 T02590215=

METAR KSWW 181515Z AUTO 19010KT 10SM CLR 27/22 A3014 RMK AO2 T02650216=

METAR KSWW 181535Z AUTO 21013G18KT 10SM CLR 29/21 A3015 RMK AO2 T02860214=

METAR KSWW 181555Z AUTO 20010KT 10SM SCT080 29/21 A3016 RMK AO2 T02870208=

METAR KSWW 181615Z AUTO 21012KT 10SM OVC080 29/21 A3016 RMK AO2 LTG DSNT E T02850205=

METAR KSWW 181635Z AUTO 23006KT 10SM BKN080 OVC100 29/20 A3016 RMK AO2 T02850204=

Accident occurred at 1645 UTC (1145 CDT)

METAR KSWW 181655Z AUTO 24007KT 10SM BKN080 BKN090 29/21 A3016 RMK AO2 T02880206=

METAR KSWW 181715Z AUTO 20008KT 10SM SCT070 BKN080 BKN090 30/20 A3016 RMK AO2
T02980202=

METAR KSWW 181735Z AUTO 20008KT 10SM SCT075 SCT100 30/21 A3015 RMK AO2 T02950208=

METAR KSWW 181755Z AUTO 20008KT 10SM CLR 30/20 A3015 RMK AO2 T02980201 10299 20223=