



RECORD OF CONVERSATION

Mitchell Gallo
Aviation Accident Investigator, NTSB IIC
Central Region

Person Contacted: David Nannarone, Aircraft Builder
NTSB Accident Number: CEN18FA126

Narrative:

During a telephone conversation, David Nannarone stated that the accident airplane had a stall speed of about 45 mph, and he would not fly the airplane below 50 mph. He stated that he would maintain a speed of about 63 mph when the airplane crossed the runway numbers and that he landed the airplane only on hard-surface runways that were at least 2,500 ft in length.

Taken by:

Mitchell Gallo