



RECORD OF INTERVIEWS

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN18FA160

Mrs. Lorna Belair, the wife of the pilot, provided the following information:

- The pilot visited a medical doctor about every three months, and she considered him to be very healthy.
- Her husband appeared to be in good spirits and mentally and physically stable during the period prior to the accident.
- The pilot had experienced chest pains three years prior to the accident. After being checked out by medical professionals and told that his heart was strong, the pilot hadn't had any cardiac oriented issues since.
- His most recent ECG, conducted in 2014, had normal results.

Mr. Paul Fink, the son of the passenger, provided the following information:

- He was not aware of any cardiac issues that his father had.
- His father appeared to be in good spirits and mentally and physically stable during the period prior to the accident.
- During the last two years, he noticed that his father would get tired more easily during walks and while climbing stairs.
- His father had started to frequently take a nap in the afternoon.
- His father took a lot of vitamins and natural supplements.