



Photo 1 – The wreckage of N622DP rests on its left side after striking trees and impacting the ground between the 16th and 18th holes at the Silo Ridge Golf and Country Club, Bolivar, Missouri.



Photo 2 – Rear view of N622DP. Fairway is in background.



Photo 3 – The instrument panel of N622DP at the accident site.