



Photo 1 – Aerial view of the airplane partially submerged in the Missouri River (courtesy of the Morton County Sheriff's Office).



Photo 2 – Aerial view looking to the north of the airplane partially submerged in the Missouri River and the surrounding area (courtesy of the Morton County Sheriff's Office).



Photo 3 – View of the recovered airplane (courtesy of the Morton County Sheriff's Office).



Photo 4 – View of the left side of the airplane.



Photo 5 – Interior view looking outside of the airplane from the left seat.



Photo 6 – Left seat view of the cockpit. The carburetor temperature system, installed on the right side of the cockpit, is highlighted with a red circle.



Photo 7 – View of the carburetor temperature system.



Photo 8 – View of the camera and the lens utilized by the pilot.



Photo 9 – View of the engine (courtesy of Lycoming Engines).




Photo 10 – View of the top portion of the carburetor (courtesy of Lycoming Engines).




Photo 11 – View of the lower portion of the carburetor (courtesy of Lycoming Engines).