



Transport
Canada

Transports
Canada

TP 1406
(07/2003)

**AIRCRAFT
JOURNEY
LOG**

**CARNET
DE ROUTE
D'AÉRONEF**

TC-1000110



Canada

FLIGHT RECORD

Other - Autre

Record of time - Fiche de temps

Journey - Route

Time - Temps

4068⁷

4070⁹

4072⁴

4074⁵

4076⁴

4076⁷

4078¹

4079⁹

4080⁴

4082¹

4083⁹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

4084¹

DOSSIER DE VOL

Maintenance

Defects
Défectuosités

Rectification

R/H Transfer pump intermittent, unit replaced with new leak checked by us. Faults noted. The described maintenance has been C/B IAW the applicable standards of airworthiness.

OIL PRESSURE at 66 PSI left engine
AUTO Pilot ACTING UP STEERING to the RIGHT

48108-1 oil filter - oil change Phillips 20400 xrc

R/H oil filter Zep & Ford clean oil change W Phillips 20400 xrc

Noted Installed CH48108-1 oil filter L/R Engine

align Rod ends lubricated

engines Run No defects Noted after the R/H starter drive shown - end

CHAPMAN AIRCRAFT SERVICE LTD.

C-GLKX

Cessna 340A

S/N340A1221

4084.1TTAF

L/H Engine: TTSO-520-NB S/N 521348

Completed repair of #2 Top ignition lead at magneto due to broken shielding by shortening cable 1/4". Completed Engine run-up, no defects noted.

R/H Engine: TTSO-520-NB S/N 522388-H

Removed starter drive P/N 642085A4 S/N 602101 and installed 642085A2 S/N CAM16-355 starter drive. Verified that Starter drive is getting good oil flow. Verified that starter is engaging/releasing as per CAM instructions dated Nov 22, 2016. Engine motored over and verified that starter drive disengages properly. Reinstalled hoses and Air filter housing assembly removed for access for starter drive. Reinstalled Starter MHJ-40035 S/N G051192 that was removed May 16, 2018 from this engine. Checked starter output friction and found at 4.5in-lb. Installed 2870 EGT probe S/N 114043 on #1 Exhaust. Completed Engine run-up, no defects noted.

Airframe: Adjusted friction on nut on Pilots L/H window latch by squeezing and reinstalling. R/H Aux fuel tank defueled, replaced A8150B S/N 05255 Fuel pump with S/N 84282 using two 32448 knife connectors and oen36160 ring terminal. R/H aux fuel tank refueled, leak check carried out, covers reinstalled.

The maintenance described has been performed in accordance with the applicable standards of airworthiness.

F. Chamberlain

June 21, 2018

*Dates where applicable — Supprimer si ce n'est pas applicable

**Total time since new — Temps total depuis neuf

DOSSIER DE VOL

FLIGHT RECORD			Journey - Route		Record of time - Fiche de temps		Other - Autre
Date	Crew - Equipage Pilot / Capitaine Crew / Équipier	From De	To À	Air Décollage	Dwell Atterrissage	As time Temps-air	TTSN**
2/6						4084 ¹	
2/6	PECKHAM	CNFB	CYRP	1952	2009	0.3	4084 ⁴
2/6	PECKHAM	CYRP	CYQB	0938	1100	1 ⁴	4085 ⁸
2/6	PECKHAM	CYQB	CYRP	1134	1300	1 ⁴	4086 ²
5/6	PECKHAM	CYRP	CYGD	1225	1417	1 ⁹	4088 ¹
20/6	PECKHAM	CYGD	CYRP	1707	1837	1 ⁵	4089 ⁰
1/7	PECKHAM	CYRP	CYQB	1828	1938	1 ²	4090 ⁸
1/7	PECKHAM	CYQB	CYRP	2021	2228	1 ⁹	4092 ¹
2/7	PECKHAM	CYRP	CYGG	0853	0923	0 ⁵	4093 ²
4/7	PECKHAM	CYGG	CYRP	1630	1705	0 ⁶	4093 ⁸
10/7	PECKHAM	CYRP	CYQB	1210	1430	2 ³	4096 ¹
10/7	PECKHAM	CYQB	CYTZ	1505	1738	2 ⁷	4098 ⁸
12/7	PECKHAM	CYTZ	CYQG	1052 1052	1314	2 ⁴	4101 ²
12/7	PECKHAM	CYQG	CYTZ	1341	1448	1 ¹	4102 ³
12/7	PECKHAM	CYTZ	CYRP	1521	1631	1 ²	4103 ⁵
14/7	PECKHAM	CYRP	CYTZ	0534	0648	1 ²	4104 ⁷
17/7	PECKHAM	CYTZ	CYRP	0730	0833	1 ⁰	4105 ⁷
18/7	MASONDUVE	CYRP	CYKF	0730	0900	1 ⁵	4107 ²
18/7	MASONDUVE	CYKF	CYRP	1400	1730	1 ⁵	4108 ⁷
19/7	PECKHAM	CYRP	CYTZ	0718	0833	1 ²	4109 ⁹
20/7	PECKHAM	CYTZ	CYRP	08235	1338	1 ⁰	4110 ⁹
21/7	PECKHAM	CYRP	CYGG	0753	0926	0 ⁵	4111 ⁴
21/7	PECKHAM	CYGG	KDTW	0846	1051	2 ¹	4113 ⁵
21/7	PECKHAM	KDTW	KLAN	1125	1200	0 ⁰	4114 ¹
21/7	PECKHAM	KLAN	CYRP	1258	1540	2 ⁷	4116 ⁸
22/7	Oil drained and replaced with 11 l Phillips 20w50x on both engines. Replaced LH vacuum pump P/N 442 CW S/N 175024 check carried out. No defects noted.						Rgt

*Delete where inapplicable — Supprimer si ce n'est pas applicable

*Total time since new — Temps total depuis neuf

[illegible]

Not scheduled maintenance
Practice maintenance planifié

Due
Echéance(14) / cycles
(15) / cycles

DOSSIER DE VOL.

[illegible]

**Total time since new — Temps total depuis neuf

752

FLIGHT RECORD		Journey - Route		Record of time - Fiche de temps		Other - Autre	
Date	Crew - Equipage	From - De	To - A	Up - Décollage	Down - Atterrissage	Air time - Temps-air	TISN ¹
Passenger - Passagers		Cargo - Marchandises		Remarks - Remarques			
9/4	MAISONNEUVE	CYTZ	CYHM	1534	1552	0 ³	4159 ⁸
9/4	MAISONNEUVE	CYHM	CYRP	1900	2019	1 ³	4161 ¹

**Total time since new — Temps total depuis neuf

[illegible]

Due
Echance