

2:46 PM 10-13-17

Russell Oberq

Flying S.E. west of Ft. Collins - Engine Sputtering

Symptoms of Fuel exhaustion. Been in the air 1 hr - Took off w/ 39 gal. Try to keep engine running by pumping throttle. Losing altitude - finally had to commit to forced landing. Got it on the ground rolling - Maybe 60 mph - had to brake hard - tipped nose down - Flipped it over

Got out ok -

P VAS

Hangar 1 H South side Vancor Brand