



Photo 1 – Oil residue on taxiway



Photo 2 – Oil residue on taxiway




Photo 3 – Rear of engine and generator




Photo 4 – Rear of engine



Photo 5 – Hole above #1 cylinder