

Communication Summary

12/5/2017

Information from: Zachary D. Oakley A.A.E.



Summary & Factual Information: Mr. Oakley was asked to confirm how much fuel exited the airplane when it impacted terrain. He, in part, reported, “From talking to the Chief and the rest of the guys that were on scene prior to my arrival (6:30pm) as well as my own knowledge of the scene there was never any visible fuel exiting the aircraft while it was sitting on the ground or while it was being lifted and moved. There was a slight fuel smell around the aircraft but we never saw a fuel pooled anywhere.”

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator