



Photo 1 – N515BW in school ballpark after forced landing.



Photo 2 – N515BW against chain link fence.



Photo 3 – Tree that was struck during forced landing.



Photo 4 – Empty fuel tank.