

Central Flying Service, Inc.

1501 Bond Street
Little Rock, AR 72202
Phone: 501-375-3245 Fax: 501-375-7274
Federal I. D. 71-0280254

Invoice: 041808964

Opened: 3/14/2018
Closed:

Sold To: NTSB
C/O John Brannen

Aircraft Number: N4654D Type: G35 S/N: D-4836

Item: 1

Problem:

Check balance of ruddervators.

Action Taken:

Checked balance of ruddervators as provided; in accordance with Beechcraft Bonanza Series Shop Manual, Chapter 3. Left ruddervator is tail heavy, 19.04 in. lbs. Right ruddervators is tail heavy, 18.76 in. lbs. Both within limits, per Shop Manual.

Charges This Item:

Item: 2100

Problem:

Comply with Preliminary Inspection.

Action Taken:

Preliminary Inspection complied with. (Reference Repair Station Manual Section 8.7)

Total For This Item: \$ N/C

Totals:

SubTotal:

Sales Taxes:

Charges:

Amount Remaining:

THANK YOU FOR YOUR BUSINESS!

PAYMENT TERMS

Prices quoted are in US Dollars. Preferred methods of payment include cash, wire transfer, or certified bank draft. A three percent (3)% service fee will be added for payments made by credit card of \$10,000.00 or more.

This invoice is due and payable upon receipt. Any disputed amount should be addressed in writing within ten days of receipt of invoice. A finance charge will be added to any undisputed charge that is not paid within 30 days.

Failure to make a payment may result in a late payment fee up to \$25.00 in addition to the finance charge.

CORE CHARGES:

A. EXCHANGE CORE BILLED: Our vendor has billed us for the exchange core. Pending final vendor evaluation of your core, you may receive a credit, possibly in full. The amount of the credit will be based on any above and beyond normal overhaul charges.

Central Flying Service, Inc.

1501 Bond Street
Little Rock, AR 72202
Phone: 501-375-3245 Fax: 501-375-7274
Federal I. D. 71-0280254

B.EXCHANGE CORE NOT BILLED: Exchange prices are contingent on your core being accepted by the vendor. If your core is rejected, you will receive additional billing at a later date.

OVERHAUL CHARGES:

Overhaul prices are for standard overhauls. If your unit requires parts other than the standard overhaul parts, you will receive additional billing at a later date.

LIMITED WARRANTY

Central Flying Service, Inc. warrants that the services performed will be free from defects in workmanship under normal use for a period of time as stated in our published warranty policy. A copy of the policy is available upon request. All services performed shall comply with the applicable FAA regulations in effect as of the date the work was performed. Central must be notified immediately in writing of any defect upon discovery. All warranty work must be performed at Central Flying Service, Inc. The amount of the warranty is limited to the amount paid for the subject part or repair.

All parts and components will be limited to the vendor warranties. Central disclaims all warranties, either express or implied, including any implied warranty or merchantability or fitness for a particular purpose.

This warranty does not apply to the following: 1. Normal wear and tear. 2. The consequence of accidents, negligence, abuse, or alteration, other than by Central Flying Service. 3. The cost associated with moving the aircraft to Little Rock for repairs. 4. Customer furnished parts, material, or equipment. 5. The labor to replace a defective part.

In case of any discrepancy between these statements and our published warranty policy, our published warranty policy shall prevail.

THANK YOU FOR YOUR BUSINESS.