



Photo 1 – N540JH



Photo 2 – Engine on N540JH



Photo 3 – Hole in Engine on N540JH