



Photo 1 – Accident Site (Courtesy of Pilot Receiving Instruction)



Photo 2 - Damage to Fuselage and Main Rotor Drive Shaft Under Housing (Courtesy of FAA)