



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: May 21, 2018
Person Contacted: Greg Boom, Rocky Mountain Aviation
NTSB Accident Number: CEN18LA180 – Broomfield, Colorado

Narrative:

Mr. Boom stated that the accident airplane, N4EJ, was recovered to Rocky Mountain Aviation after the accident. He stated that the right brake line was broken near the upper end of the landing gear strut near the strut fairing.

----- End of entries -----