



Photo 1 – Damage to Nose Section of the Airplane



Photo 2 – Damage to Horizontal Stabilizer and Rudder



Photo 3 – Reattached Left Rudder Spring