



VIDEO SUMMARY

Mitchell Gallo
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN18LA228

Narrative:

A video showed the airplane takeoff and after liftoff it entered a right roll to about 45-degree bank angle within about one wingspan height above the runway. The video showed both flaps extended and both propellers rotating.

Mitchell Gallo