

DATE

19__

RECORDING
TACH
TIMETODAYS
FLIGHTTOTAL
TIME IN
SERVICE

DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS
ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF
MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

Satnan Avionics

Joe Foss Field
Sioux Falls SD

Airframe Log

DATE	MAKE/MODEL	TACH / HOBBS	TOTAL TIME	REGISTRATION	SERIAL NUMBER
9/22/17	BEECH/V35	5815.4	5815.4	N228Q	D-8135

Conducted Annual inspection IAW Beechcraft manual P/N 35-590096B21 sec 7 checklist. Opened access panels, floor boards, seats, spar covers, wing bolt covers, and rear bulk head and inspected, lubricated all pivot points, pulleys, rod ends, and cables. Replaced landing light circuit breaker switch with new W31M-20. Light check satisfactory. Replaced Right exhaust collector with new BES0004 S/N 000149-0005 using new R200 hardware kit and new exhaust gaskets 652458 (3). Replaced vacuum system filters AAR3-5-1 and AAD 9-14-5. Inspected landing gear and lubricated as needed. Placed aircraft on jacks and performed retraction, extension and emergency extension procedures. Verified proper operation of "Magic Hands" safety switch mechanism with no defects noted. Checked gear sector limit switch rigging 1/4 turn up, and 1/4 turn down. Inspected brake linings, brake caliper and tires. Serviced all struts with MIL 5606 hydraulic fluid and nitrogen as needed. C/W 91.207 (d) by inspection and operational check. Battery replacement due 3-2018. Replaced air filter with new BA7112. AD 94-20-04 next due 5896 AFTT. AD 95-04-03 next Due 6186.7 AFTT. AD89-05-02 next due 5896 AFTT. C/W AD 76-07-12 by operational check of magneto OFF position. Next due 5915.4 AFTT. C/W 07-08-08 by lubrication of uplock rollers. Next due 5915.4 AFTT.

I certify that this aircraft has been inspected IAW an ANNUAL inspection and Federal Aviation Regulations and is found to be airworthy at this time. Details on file at this agency. W.O.# M3647

Signed

Tyler Ellis

IA #

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
126/18				Replaced ELT batteries w/ 8 ea Duracell D batteries Due 2-28-20
				[REDACTED], P-SEL Cert # [REDACTED] owner, <u>Calkins Aero Service Inc.</u> West Houston Airport 18000 Groeschke Rd. Houston, TX 77084 DATE: 02/08/2018 N228Q TACH: 5854.59 WORK PERFORMED: AIRFRAME REPLACED R/H FUEL CELL WITH NEW PN#35-380135-10E SN#564. I certify that the work performed was carried out in accordance with 14 CFR 43 and was determined to be in an airworthy condition. Details on file at Calkins Aero Repair Station under WO# 27583 Calkins Aero Service Inc. FAA Certified Repair Station [REDACTED] No. GK2R849K signed [REDACTED]
				<u>Calkins Aero Service Inc.</u> West Houston Airport 18000 Groeschke Rd. Houston, TX 77084 DATE: 03/05/2018 N228Q TACH: 5873.53 WORK PERFORMED: REMOVED OXYGEN BOTTLE AND LEFT IN BAGGAGE COMPARTMENT. WEIGHED 20LBS 10OZ. REMOVED SINGLE YOKE AND INSTALLED DUAL YOKE. I certify that the work performed was carried out in accordance with 14 CFR 43 and was determined to be in an airworthy condition. Details on file at Calkins Aero Repair Station under WO# 27641 Calkins Aero Service Inc. FAA Certified Repair Station [REDACTED] No. GK2R849K signed [REDACTED]