

Propeller Log

Satnan Avionics

Joe Foss Field
Sioux Falls SD

DATE	MAKE/MODEL	TACH / HOBBS	TOTAL TIME	SPOH	REGISTRATION	SERIAL NUMBER
9/22/17	MCCAULEY 3A32C406-C	5815.4	1436	451.8	N228Q	983362

Conducted an Annual inspection IAW McCauley service manual and FAR 43 App D. C/W AD2007-08-04 IAW ASB248. Verified placard installed.

I certify that this propeller has been inspected IAW an ANNUAL Inspection and Federal Aviation Regulations and is found to be airworthy at this time. Details on file at this agency. W.O.# M3647

Signed

[Redacted Signature]

IA #

[Redacted IA #]

Tyler Ellis

May 2, 2018

W/O 18971

RESEAL REFINISH BENCH TEST AND STATIC BALANCE C/W AD NOTE 2007-08-04. A.S.B 248 McCauley Propeller (DWG: 3A32C406-C) (S/N: 983362) I/A/W McCauley MANUAL # MPC400, BOM100. Mechanic making installation must comply with FAR 43.9. Repair Station DM2R773K certifies this propeller is airworthy with respect to the work performed.

SIGNED:

[Redacted Signature]

San Antonio Propeller Service


CUSTOM AVIATION SERVICES

12229 BONANZA PLACE, BROOKSHIRE, TX. 77423

Beechcraft V35, N228Q, Ser.#:8135, Tachometer: 5929.7, Hobbs: 1384.0

Date: 05/22/2018

This propeller, McCauley, Ser.#: 983362 was repair by San Antonio Propeller Service. See work order and repair ticket. C/W AD 2007-08-04 at this repair. Crankshaft oil galley to propeller governor was de-sludged. Propeller was installed with new O ring seal, nuts and washers. Torque was set to McCauley requirements. Run up for leak check and operation was performed. Repair and installation of this propeller is determined to be airworthy and aircraft is returned to service.


Lyle E Green AF 